

प्रमाणित किया जाता है
कि मापी पुस्त में मशीन टैकी 100
एक सौ पृष्ठ हैं जिसे श्री बाबू
मन मोहन सिंह ने अमिता को
अवल प्रमण्डल पकडीदयाल के पास
केपटना से निगति किया जाता है

Amg
कार्यपालक अधिकारी
ग्रामीण कार्य विभाग
प्रमण्डल पकडीदयाल
18.7.17

Schedule XLV Form No.-134

R.W.D. PAKARIDAYAL. DIVISION
R.W.D. PAKARIDAYAL SUB-DIVISION
PATANI

MEASUREMENT BOOK

765

Name of officer _____

Date of first entry _____

Date of last entry _____

4th year Maintenance	
15/11/21 - Maintenance of Road from Parsauni to Janorath Bownchali MAGSYSC	
Block - Patali	
Agency - Waterbiter Construction Company Pr - Sonjay Kumar Sports club road, Chhatani Mothari, Eche form	
Approved - 79520/2018-19	
Actual Date of completion - 8.02.2020	
Maintenance work has been done by Agency -	
Continuation	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Maintenance of Earthwork					
Similar to 11.7 as per spec.					
2 x 8 x 12.60 x 0.75					= 157.20
2 x 12 x 16.30 x 0.60					= 234.20
2 x 14 x 11.84 x 0.65					= 197.28
2 x 14 x 14.10 x 0.50					= 197.40
					1
				T	758.58 y ²
2. Rebooshing of drain cut with soil					
2 x 6 x 11.90 x 0.80 x 0.30					34.27
2 x 8 x 10.40 x 0.70 x 0.30					34.94
2 x 10 x 9.20 x 0.75 x 0.30					41.40
2 x 12 x 8.00 x 0.65 x 0.30					37.44
2 x 15 x 6.25 x 0.55 x 0.30					30.88
				T	178.93 y ²
3. Main 9 with road including filling					
6 x 4.80 x 1.60					= 46.08
8 x 6.70 x 0.90					= 48.24
10 x 7.10 x 1.20					= 85.20
16 x 2.39 x 0.20					= 7.64
				T	187.16 y ²
4. Repair of pot holes					
tail material					
6 x 4.80 x 1.60					= 46.08

Continuation

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	8	6.70	0.90	-	48.24
	10	7.10	1.20	-	85.20
	16	2.39	0.20	-	7.64
				T	187.167 ²
5. Patch 1 repair H.P. culvert					
by 1-way					
	6	4.80	1.60	-	46.08
	8	6.70	0.90	-	48.24
	10	7.10	1.20	-	85.20
	16	2.39	0.20	-	7.64
				T	187.167 ²
6. Patch 1 H.P. culvert					
by 1-way					540
7. Cutting 1 branch 1.					
1-way					1440
8. Cutting 1. Shrub 1.					
1-way					2890.40
9. Trimming 1 from 1					
1-way					
	2	20	30.00	0.25	300.0
	2	20	30.0	0.30	360.0
	2	20	30.0	0.40	480.0
				T	1140.072
				but	1118.430 ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
10	White washing 1 part				
	well				
Top.	10x	6.150x	0.40		24.60
End.	20x	0.40x	0.60		4.80
S. for	10x	6.150x	0.60		36.90
					T 66.30 y ²
					42.35 m ²
11.	Gravel 1.200 x 4x4				
	stone				0.416 km
12.	Gravel 1.4 x 5m				
	by way				6.600 km

Ans.	Ans.		
18-2.24	18-2.24.		
J. B.	A. E.		
	Abstract of cost.		
Y ₂	Gravel 1 part		
	well		
	P. 2)		
758.587	54.3)	9	41244.2
2/1	Restoration of access		
	with soil		
	P. 2)		
178.937	665.25	1	65354.2
2/5	Gravel 1 part		

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	incl				
		1.22			
187.167 ² @ 1. 295.43				1	74009~
4/4 Repair & put					
loose y. b. i.					
		P. 28			
187.167 ² @ 1. 290.47				1	54289~
5/5 Patch & put					
fill & put					
		P. 28			
187.167 ² @ 1. 274.30				1	51338~
6/7 H.P. culch.					
rest - easy					
		P. 28			
5 No ① 1131.64				1	5658
7/12 Cutting & brush					
tree					
		P. 28			
14 No ① 107.48				1	1505~
8/12 Cutting & brush					
12 y. way					
		P. 28			
28.904 No ① 6260				1	191~
9/14 Trenching					
work					
		P. 28			
1118.439 ² @ 1. 2.20				1	2461~

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
10/15		White	measuring	1000	
		P.	29		
43.357		16280			
11/19		2000			728
		8.	29		
0.416 km		249			312
12/9		by way			
		P.	29		
0.600 km		1087-63			7178

					304267
					335
					303932
18.2.24		18.2.24			
J.E.		A.E.			
Total - 127.206 y ³					
Grim - 5.053 y ³					
S-d - 1.122 y ³					
Curt - 0.093 y ³					
Bike - 0.801 y ³					