

4th year maintenance

N/W 1 - Mainline & 1 - from Karschiya

to Bahua (Karschiya)

MMSY 'C'

Block - Dhoke.

Agency - Sushil Kumar Jha.

Barhore Sivan Dhoke

E. Champaran.

Agreement No - 33 SBD/2018-19

Actual Date of work 30.10.2019

Maintenance work has

been done by

Agency

Continuation

Abstract & cost

Y, Restoration & Reins. els

with soil

P.

108.35 7³ @ 8. 365:25 6. 39575.

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
7/2	Maint of Earth				
	shldr filling				
	P.				
440.75 m ² @ 9	54:37			6.	23964.
2/4	Maint of way				
	including				
	P.				
96.11 m ² @ 9	426:61			8.	41001.
4/3	Repair to bot hole				
	by man				
	P.				
96.11 m ² @ 9	300:71			8.	28901.
7/5	Patch Repair on				
	already filled				
	P.				
96.11 m ² @ 9	284:92			8.	27384.
6/7	Maint of H.P culvert by				
	R. way				
	P.				
1 NO @ 8.	1131:64			8.	1132.
7/10	Cutting of branch of				
	tree				
	P.				
8 NO @ 9.	107:48			8.	860.
8/13	Cutting of branches of				
	g. way				

Continuation

Gen. XLV-Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		P.			
17.50 H. @ 9	6260		9.	116-	
9/14	Trimming & grass and well				
		P.			
677.25 y ² @ 8	2,220		9.	1490-	
10/15	While working & borehole well				
		P.			
20.64 m ² @ 8.	16,80		9.	347.-	
11/11	Mainly & rocky & km stone				
		P.			
0.252 km @ 9,	749 = 0		9.	189 -	
12/9	Mainly & low side by way				
		P.			
3.300 km @ 9.	1087 = 63		9.	3589 -	
			9.	168548 :-	
less 0.03% below w h			9.	168497 :-	
Summed by					
05/12/23					
AB					