

कार्यपालक अभियन्ता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल, बायसी

पत्रांक 1910(316/2) बायसी / दिनांक 13/08/2024

प्रेषक,

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बायसी

सेवामें,

अपर मुख्य कार्यपालक पदाधिकारी-सह-
सचिव,
ब्राडा, पटना।

विषय : मुख्यमंत्री ग्राम सम्पर्क(सामान्य) योजनान्तर्गत प्राधिकार पत्र तथा आवंटन भेजने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि मुख्यमंत्री ग्राम सम्पर्क (सामान्य) योजनान्तर्गत मांग पत्र विहित प्रपत्र में तैयार कर आपके आवश्यक कारवाई हेतु समर्पित किया जाता है।

अतः अनुरोध है कि संवेदकों का भुगतान हेतु बैंक प्राधिकार पत्र तथा आवंटन निर्गत करने की कृपा की जाय।

अनु० -मांग पत्र, Utilisation Certificate

विश्वासभाजन

13/08/2024
कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बायसी

Niveler Mr.
07/08/24.

Name of Circle :- Purnia
Scheme Head:- JMMGSY(GEN)

S.No.	Year	Name of Road	Name of Contractor	Length of Road	Estimated Cost Agreement value (in Lacs)			Fund Received Till Date(in Lacs)	Fund Expence Till Date(in Lacs)	Demand (in Lacs)	Remarks
					Main Work Amount	Maintenance	Total				
1	2020-21	Gariya More to Muslim Tola	Amarpur Construction Co. Private Limited	2.220	352.46491	20.30611	372.77102	109.96365	242.00410	132.04045	On-going

Sr, Division Accounts officers,
RWD, Works Division, Baisi

Executive Engineer,
Rural Works Department,
Works Division, Baisi

13/08/24
130824
0708/24.

Division- Baisi

(See Government of India's Decision (I) below Rule -150)
Form of Utilization Certificate upto the month of July 2024

PIU – RWD, Works Division, Baisi.

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

- i. Works have been supervised by Executive engineer / Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive engineer / Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.
- v. All other codal formalities have been observed.

- i. Construction of Road Works.
- ii. Construction of CD works.

13/08/2024

Executive Engineer
RWD, Works Division, Baisi