

Refresh/28

MMGSY (SC)

19

~~Payee ID PT0071560~~

Schedule XLV-Form No. 134

New Payee ID- PT1482596

Salarpur Bigha Harijan Tola L-25-DIVISION

peil to Thurggi Thopd'schaf SUB-DIVISION

MEASUREMENT BOOK

रहायक समिति दानिया

7392

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1st year maintenance				
Name of work:-	maintenance of Road from				
	Salarpur Bigha Harigan				
	Tola L-25 Rd to Jhanggi				
	Jhokdi school ender				
	mm(454) (54)				
Agency:-	Rajnish Kumar, Charan Bha-				
	- was. H. N. 77, near Durga				
	Chokk, R220 rd-15, Indore-				
	- Puri, P.O- Keshari Nagar,				
	P.S- Patlibata, Patli-24				
Agreement no-	22/500/2020-21				

Rate Approved - 5.2970 below					
Date of commencement - 22/09/2020					
Date of completion - 01/06/2021					
Actual date of completion - 29/08/2023					
Date of Measurement - 5/08/2024					
Work done					
Item (1) Restoration of rain water					
Beds with soil - do etc					
1x	6.00	1.00	0.30	=	1.80 m ³
1x	15.00	0.70	0.30	=	4.05 "
2x	10.00	0.75	0.30	=	4.50 "
3x	7.00	0.90	0.30	=	5.67 "
1x	12.00	0.80	0.30	=	2.88 "
3x	3.15	1.00	0.30	=	2.84 "
					21.74 m ³

Continuation

[illegible]

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item (4) Maintenance of H/P Culvert -- do -- etc.					
					Qty = 2.00 nos.
Item (5) maintenance of road sign --- do --- etc.					
					Qty = 0.08 km.
Item (6) Maintenance of 200 m 2 km Stone -- do -- etc.					
					Qty = 4.09 km.
Item (7) Cutting of branches of trees & shrubs do - etc.					
					Qty = 1.00 Nos.
Item (8) cutting of shrubs from road way -- do -- etc.					
					Qty = 5.00 Nos.
Item (9) Trimming of grass & weeds -- do -- etc.					
					Qty = 1.98 m ²
	J.E. 5/08/24				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Material statement</u>					
(1) Earth	—				47.73m ³
(11) Stone	—				0.33m ³
(14) Emulsion	—				0.102m ³
(15) Bidmen (80/100)	—				0.014m ³
<u>Graph</u>					
5/08/24 J.E.					
<u>Soil storage</u>					
(1) Earth	—	34.81m ³			
Qty = 47.73m ³					
10% of 34.81m ³	—	3.48m ³			166 = 0.2
(1) Patch repair	—	15.66m ²			
Qty = 10.07m ²					
10% of 15.66m ²	—	1.57m ²			16 = 0.2
					132 = 0.
<u>Graph</u>					
5/08/24 J.E.					
5/8/24 J.E.					

Continuation

PTD



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF Cost					
(1) Reception of rain cuts/ Brooms with soil-do-etc.					
21.74 m ³ vide T.M.B.P. (76)					
at 404 = 06/m ³ — Rs					8784 = 00
(2) Making up of drains/ Shoulder stripping ex- cess soil—do—etc.					
209.45 m ² vide T.M.B.P. (77)					
at 60 = 20/m ² — Rs					12626 = 00
(3) Patch repair on area — dry filled pot holes					
with 75 mm 100 mm thick mix seal surfacing —do—do—etc.					
10.07 m ² vide T.M.B.P. (77)					
at 274 = 67/m ² — Rs					2766 = 00
(4) Maintenance of Home pipe Culvert-do-etc.					
2.00 nos. vide T.M.B.P. (78)					
at 1166 = 58/each — Rs					2333 = 00
(5) Maintenance of road signs—do—etc.					
0.08 km. vide T.M.B.P. (78)					
at 1104 = 58/km — Rs					88 = 00
					1
					at 926597 = 00

Continuation

J.E. Continuation