

1st year maintenance work.

50

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: - To 2 (Salpur Manichha to Salpur Manichha Ghumbar and Mali chh.					
Agency - Krishna naman					
Reg no - 78/SRD/2020-21					
Date of commencement - 18/08/2020					
Date of completion - 17/08/2020					
Actual date of completion - 28/01/2022					
(Revised entry)					
Restoration of rain cuts					
9 x 30 m x 0.25 x 0.25 = 33.075					33.075
Unit R =					30.38 m ²
2) Maintenance of Leather Shoulder					
2 x 4 x 30 m x 0.07 = 174.6					174.6
Unit R =					168.75 m ²
3) Maintenance of mix road surfacing					
6 x 2.80 m x 1.0 m = 13.80 m ²					13.80 m ²
Maintenance of bitumen surface road					
Maintenance of H.P. inverts					
R = 1 NO					
4) Maintenance of slab type inverts					
R = 3 NO					
5) Maintenance of 20cm and 15cm stone					
R = 1.204 cum					

15/4/23
SE

Continuation

16/4/23
SE

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of rain water Qty vide TWR P No (50)					
B = 30.28 m ² @ 386.44/m ² =					11731.00
(2) Maitene of barthen shoulder Qty vide TWR P No (50)					
B = 168.75 m ² @ 57.24/m ² =					9680.00
(3) Maitene of rain pen surfacing Qty vide TWR P No (50)					
B = 12.80 m ² @ 288.36/m ² =					3703.00
(4) Maitene of H.P. culverts					
Qty vide TWR P No (50)					
B = 1 No @ 1180.64/No =					1181.00
(5) Maitene of slab type culverts Qty vide TWR P No (50)					
B = 200 @ 2329.21/m ² =					6988.00
(6) Maitene of 20m and 10m stone Qty vide TWR P No (50)					
B = 1.21 km @ 726.47/km =					879.00
					3411.00
					Add 6% cost 1% = 341.00
					Add 12% cost = 4093.00
					Add. Signature = 90.00
					Total = 38636

Continuation

[illegible]