

Abstract of east 5th year.

29

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	D.
<u>① Restoration of Rain</u>				
early				
Q-VTNB/26② =			49.37H	
P27⑤ =			49.20H	
P28⑥ =			35.92H	
			134.49H	
cf 359.74/1H			R -	4838/2m
<u>② Maintenance of earthen</u>				
Shoulder				
Q-VTNB/25① =			258.22H	
P26③ =			258.86H	
P27⑤ =			230.37H	
			747.45H	
cf 53=91H ² - R			40295=0	
			R -	88,676=0
Less 0.37% below -			328=0	
			R -	88,348=0
19/6/24			8/10/24	
S.E.			Av	
cf				
Verifed				

5th Year Maintenance

25

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Bikrama Ram house to Daroga Sah house under GTSN					
Agency- Sri Sanjeev Kumar Denny					
Agreement No- 31 SBD/2018-19					
Date of start- 12/09/2018					
Date of Completion- 11/06/2019					
Actual date of Completion- 10/06/2019					
5th Year Maintenance 11/06/2023 to period 10/06/2024					

① Maintenance of earthen shoulder

1	X	6.50	X 1.10 =	7.15M
2	X	7.40	X 1.25 =	17.50M
2	X	8.40	X 1.20 =	19.20M
1	X	7.25	X 1.15 =	8.34M
2	X	8.10	X 1.15 =	18.63M
1	X	9.25	X 1.28 =	11.84M
2	X	8.50	X 1.20 =	20.40M
3	X	7.15	X 1.10 =	23.50M
2	X	6.75	X 1.25 =	16.87M
1	X	10.40	X 1.20 =	12.00M
3	X	11.40	X 1.10 =	36.30M
2	X	8.15	X 1.25 =	20.37M
1	X	7.50	X 1.15 =	8.62M
3	X	10.40	X 1.25 =	37.50M
Continuation				258.22M