

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल-शिवहर।

Mob No.-8986915416

Email ID-eerwdsheohar@gmail.com

पत्रांक:- 1241/अभियंता शिवहर

दिनांक:- 16/8/24

प्रेषक,

ई० चन्दन कुमार भार्गव,
कार्यपालक अभियंता।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय :-MR (3054) नई अनुरक्षण नीति 2018 के तहत पथ के अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक के संबंध में सूचित करना है कि कार्य प्रमंडल-शिवहर के अंतर्गत MR (3054) New Maintenance Policy 2018 के तहत करायें गये कार्यों के भुगतान हेतु राशि की अधियाचना विहित प्रपत्र में समर्पित की जा रही है।

अनु०- यथोक्त।

विश्वासभाजन


16/08/24
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, शिवहर
16.8.24 16.08.2024

FROM GER 19-A

[See Government of India's Decision (I) below reule-150]

Form of Utilization Certificate for the month of up to August 2024

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacsRs.)	Amount Received (in lacsRs.)	Particulars
1	Construction of Rural Roads Under MR-3054 New Maintenance Policy 2018	BRRDA Lt. No. 86 Date- 24.07.2024	3372.83671/-	Certified that out of Rs-3372.83671 Lakh of grants in aid sanctioned during the Years-2024 in favour of Executive Engineer, RWD Works Division, Sheohar Rs-3098.60712 Lakh Has been utilized for the purpose of MR-3054 New Maintenance Policy 2018 schemes as given in the margin for which it was sanctioned and that the balance of Rs-274.22959 lakh remaining unutilized at the end of the period under report.
Total:-			3372.83671/-	

2. Certified that I have satisfied my self that conditions on which the grants –in- aid was sanctioned have been duly fulfilled /are beingfulfilled and I have ,exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercise.

- (i) Work have been supervised by of Executive Engineer/ Superintending Engineer.
- (ii) periodical inspection has been conducted by of Executive Engineer/ Superintending Engineer.
- (iii) Construction materials have been tested.
- (iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/
Executive Engineer.

3 All other codal formalities.

- (i) Physical progress achieved.
- (ii) Construction of Road works.
- (iii) constructionof CD Works .


[Signature]
16/08/24
Executive Engineer
R.W.D. Works Division,
Sheohar
16.8.24
16.08.2024



Requisition Format for Scheme Head-MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)
Name of Works Division- RWD, Works Division-Sheohar.

Sl. No.	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval			Agreement Amount (in Lakh)			Date of Completion as per agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in lakh)	Up to Date expenditure as per MIS (in Lakh)	Requisition against work done (in lakh)	Remarks
					Amount (in lakh)	5 Years Routine Maintenance (in lakh)	Initial Rectification with Surfacers Renewal (in lakh)	5 Years Routine Maintenance (in lakh)	Initial Rectification with Surfacers Renewal (in lakh)	Agreement No. Date								
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/2023-24 Sheohar/02	L031 Minapur Balha to Shitalpatti Harijan Tola	31608102167	6120/04.12.2023	0.93	43.47800	9.40400	45.10387	9.45656	MBD/MR-3054/16 of 2023-24 15.03.2024	14.12.2024	3477	25	5%	0	0	45.00000	
Total						43.47800	9.40400	45.10387	9.45656						0	0	45.00000	

1. Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
2. Up - to date Physical Progress has been uploaded in MIS.
3. Certificate enclosed


 Executive Engineer,
 RWD, Works Div. Sheohar

Name of the Road-L031-Minapur Balha L023 To Sitalpatti Harijan Tola (VR14)

Name of the Contractor- RAKESH KUMAR

Length-0.930 KM

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY	IRI	Latitude	Longitude	Event
16/8/24	7:48:1	1	0.1	280	10.1	2800	3313 G	ROAD	4.4	26.53182	85.38747	Normal
16/8/24	7:48:16	1	0.1	300	10.1	3000	3540 G		4.7	26.53117	85.38816	Curve
16/8/24	7:48:58	1	0.1	320	20.2	3200	3767 G		4.9	26.53048	85.38875	Normal
16/8/24	7:49:15	1	0.1	300	20.2	3000	3540 G		4.7	26.52969	85.38934	Normal
16/8/24	7:49:58	1	0.1	310	30.3	3100	3654 G		4.8	26.52881	85.38975	Normal
16/8/24	7:50:27	1	0.1	290	20.1	2900	3426 G		4.5	26.52801	85.39017	Normal
16/8/24	7:50:56	1	0.1	310	10.1	3100	3654 G		4.8	26.52726	85.39071	Breaker
16/8/24	7:51:34	1	0.1	280	20.2	2800	3313 G		4.4	26.52644	85.39116	Curve
16/8/24	7:52:8	1	0.1	260	10.1	2600	3086 G		4.1	26.52617	85.39207	Normal

IRI	31293
AVG.IRI	3477

[Handwritten signature]
16/08/24
AE

[Handwritten signature]
16/08/24
33

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

$$Y = 0 * X^2 + 1.136 * X + 132.5$$


$$X = 2600$$


$$Y = 3086$$




कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल शिवहर।
प्रमाण-पत्र

विभागीय आदेशानुसार सत्यापित किया जाता है कि शीर्ष 3054 (नई अनुरक्षण नीति 2018) अंतर्गत L031 मीनापुर बलहा से शीतलपट्टी हरिजन टोला पथ निर्माण, प्रोजेक्ट आई०डी०- 31608102167 का मरम्मत कार्य की जाँच 100 प्रतिशत संबंधित कनीय अभियंता, 50 प्रतिशत संबंधित सहायक अभियंता एवं 10 प्रतिशत कार्यपालक अभियंता द्वारा किया गया है।


16.08.24
कनीय अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रशाखा, पिपराही।


16-08-2024
सहायक अभियंता,
ग्रामीण कार्य विभाग,
कार्य अवर प्रमंडल, पिपराही।


16/08/24
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, शिवहर।