

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance					
N/W :- Maint of Road from PMGSY Path to Baluchi (Tirahut canal)					
Agency :- Chanakya Tech Pvt. Ltd.					
Agreement No:- 39 SBD/2018-1					

Date of Work Order:- 29-11-2018

Date of Completion:- 11-06-2019

## MEASUREMENT

Plot No - 11

Restoration of Rain crest - 11

$$\text{Top} \quad 1/2 \times 25.00 \times 1.50 \times 0.60 = 22.50$$

$$\text{Bottom} \quad 1/2 \times 30.00 \times 1.50 \times 0.75 = 33.75$$

$$\text{Total} \quad 56.25 \text{ m}^2$$

$$\text{Limit} = 51.03 \text{ m}^2$$

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Door NO - 7/14					
Decorating of grass and Needs					7/5
Door NO - 37					
		$Q/H = 259.20 m^2$			
		$@ Rs. 2.08 /m^2$			
		$= Rs. 1579.16$			
Door NO - 8/15					
White washing two coats on carpet					7/5
		$Q/H = 40.32 m^2$			
		$@ Rs. 15.95 /m^2$			
		$= Rs. 643.65$			
					400.42.00
Less for below @ 10% $\Rightarrow 4004.00$					
Total =					36038.00

$\int_{-1}^1 M$	$2$	<del><math>(0)</math></del>	<del><math>10^{-20}</math></del>
$+0.06^{-20}$		<del><math>(0)</math></del>	<del><math>10^{-20}</math></del>
		<del><math>(0)</math></del>	<del><math>10^{-20}</math></del>
J.E.			45
G/S			break
<del>CAB</del>	<del>22</del>		800
<del>30111</del>	<del>22</del>		300
			111