

PMGSY SC

PM.B.No-3174

Schedute XLY-Form No. 134

पञ्जाब-पञ्जाब गुरुद्वारा से मजदुरी का कर

आगत 2019-20

Ag.No.

DIVISION

सर्वकार के मजदुरी

पञ्जाब-पञ्जाब गुरुद्वारा से मजदुरी का कर

पञ्जाब

MEASUREMENT BOOK

PM.B.No-3174

300 year Maintenance — Bell —

62

Sch. XLV—Form No. 134

Particulars	Details of actual measurement.				Contents of area
	No.	L.	B.	D.	
N/W. - Maintenance of road from Ekunda Tripur Mukhya path Se Mukund Balia Kalistanjok. Agency - Madhu Kumari Agreement No. 22 SBD/19-20 ADOC - 30/9/20.					
① Restoration of raincuts					
$9 \times 5.32 \times 1.15 \times 0.30 = 16.52 \text{ M}^2$					8
$13 \times 5.72 \times 1.15 \times 0.30 = 25.65 \text{ ''}$					
$15 \times 8.15 \times 0.90 \times 0.30 = 28.96 \text{ ''}$					
$11 \times 6.75 \times 1.05 \times 0.30 = 23.89 \text{ ''}$					
94.52 M^2					3
$\text{Added Qty } 83.28 \text{ M}^2$					
② Making up shoulder.					
$6 \times 7.10 \times 1.125 = 47.93 \text{ M}^2$					
$6 \times 8.50 \times 1.10 = 56.10 \text{ ''}$					
$7 \times 6.80 \times 1.10 = 52.36 \text{ ''}$					
$8 \times 7.05 \times 1.05 = 59.22 \text{ ''}$					
$10 \times 6.18 \times 1.10 = 67.87 \text{ ''}$					
$5 \times 2.15 \times 1.10 = 11.81 \text{ ''}$					
295.31 M^2					
③ Repair of potholes with 75 mm P.M. x 1.25.					
$7 \times 7.031 \times 1.25 = 61.52 \text{ M}^2$					
④ Patch ripap over potholes with 20 mm premix.					
$\text{Qty same as part ③}$					⑤
61.52 M^2					

Continuation

Continuation

Abstract of cost

64

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of main cut.					
Ans. (62)		83.28 M			
CR 365.25 / M ³					R 30417 = 00
② Making up shoulder.					
Ans. (62)		295.31 M ²			
CR 54.16 / M ²					R 15994 = 00
③ Repair of potholes					
Ans. (62)		61.52 M ²			
CR 387.07 / M ²					R 23814 = 00
④ Repair over potholes with 20 mm pr. concrete.					
Ans. (62)		61.52 M ²			
CR 310.54 / M ²					R 19105 = 00
⑤ Patch repair over bituminous surface.					
Ans. (63)		61.52 M ²			
CR 330.60 / M ²					R 20340 = 00
⑥ Maintenance of culvert pipe culvert.					
Ans. (63)					
5 No CR 1131.64 each					R 5658 = 00
⑦ Maintenance of culvert culvert.					
Ans. (63)					
2 No CR 2336.81 each					R 4674 = 00
⑧ Maintenance of road sign					
Ans. (63)		0.180 km.			
CR 1087.62 / km.					R 192 = 00
⑨ Maintenance of 200 M ² km stone.					
Ans. (63)					
0.240 km CR continuation					R 138 = 00
					R

Continuation