

# 4th year maintenance

48

Sch. XLV—Form No. 134

| Particulars | Details of actual measurement |   |   |   | Contents of area |
|-------------|-------------------------------|---|---|---|------------------|
|             | No.                           | L | B | D |                  |

Khairahane to Gardi

Agency = Rajan Kumar

Agg. No. = 55/GTSMY/SBD/18-19.

Dt of order = 08/02/2019.

Dt of completion = 07/02/2020.

Actual Dt of Completion = 20-06-2021.

Period = 4th year of maintenance.

(1) Restoration of Kumbhuts

do do all - c. job.

|   |      |      |      |                      |
|---|------|------|------|----------------------|
| 1 | 30.0 | 0.70 | 0.30 | 6.20 m <sup>3</sup>  |
| 1 | 30.0 | 0.60 | 0.30 | 5.40 "               |
| 1 | 30.0 | 0.90 | 0.30 | 8.10 "               |
| 1 | 30.0 | 0.80 | 0.30 | 7.20 "               |
| 4 | 30.0 | 1.20 | 0.30 | 10.80                |
| 1 | 30.0 | 0.90 | 0.30 | 8.10 "               |
| 1 | 30.0 | 0.90 | 0.30 | 8.10 "               |
| 1 | 30.0 | 1.00 | 0.30 | 9.00 "               |
| 1 | 30.0 | 1.20 | 0.30 | 10.80 "              |
|   |      |      |      | 81.50 m <sup>3</sup> |
|   |      |      |      | 73.80 m <sup>3</sup> |

2) Stripping of excess soil - c. job.

|   |      |      |  |                      |
|---|------|------|--|----------------------|
| 1 | 30.0 | 0.90 |  | 27.00 m <sup>3</sup> |
| 1 | 30.0 | 1.00 |  | 30.00 "              |
| 1 | 30.0 | 0.75 |  | 22.50 "              |
| 1 | 30.0 | 1.20 |  | 36.00 "              |
| 1 | 30.0 | 1.20 |  | 37.00 "              |
| 3 | 30.0 | 0.90 |  | 81.00 "              |

Continuation

229.50 m<sup>3</sup>

**Continuation**