

11. M.V.B. - 3/188

MEASUREMENT BOOK

11/3/1888

SUB-DIVISION

DIVISION

Schedule XLV Form No. 134  
District of Mysore  
Examination No. 2  
580/2019-20  
Date 11/3/1888

MYSORE

P.B.N.-3/1888

## 4th Year Maintenance

42

**Sch. XLV—Form No. 134**

## Measurement

## (15-1) Restoration of Raincuts /

Beams with Soil - moisture do - do

all complete job

$$2 \times 5 \text{ Nos } x 17.554 \times 1.0 \times 0.39 = 52.654^3$$

## 2) 15.2 Making up of bands/Shoulder

stripping excess soil down all

i complete job.

$$2 \times 6 \text{ N}_a \times 15.04 \times 1.04 = 1804^2$$

(3/15.5) Repair of potholes filled

width of 5 mm WB do to all

Camp etc ↑ ab.

$$10 \times 1.845 \times 1.04 = 37.50 \text{ m}^2$$

## Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④/15.3(i) Patch Repair over Pot holes do - do all complete job.					
	Qty	UTMB P. No - (42)			
		— 37.50 m <sup>2</sup>			
5/15.3(ii) Patch Repair over broken stones					
		surface do - do all complete job.			
	Qty	UTMB P. No - (42)			
		— 37.50 m <sup>2</sup>			
7/15.7(i) Maintenance of C/D					
		Works (1tune pipe culvert etc.)			
	1	2.0 N.R = 2.0 N.R			
9/15.9) Maintenance of Road signs					
	2	50.04 = 100 m			
		or 0.10 km			
10/15.11) Maintenance of 200m					
	2	km Stones etc.			
	2	× 50.04 = 100 m			
	1	× 20.0 m = 20 m			
		120 m			
		or 0.120 km			
11/15.12(i) Cutting of branches of trees & shrubs etc.					
	1	× 1.0 N.R = 1.0 N.R.			



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
1/15.1 Restoration of Rainouts/					
Bermes do - do all complete job.					
Qty NTMB P.No - (42) -					
52.65 M <sup>3</sup> @ 37.8 = 32 2/3 - 19919/-					
2/15.2 Making up of Bermes/Shoulder					
do - do all complete job.					
Qty VTM B P.No - (42)					
180.0 M <sup>2</sup> @ 58.18 2/3 - 10472/-					
3/15.3 Repair of pot holes do - do					
all complete job. Qty VTM B					
P.No - (42) 37.50 M <sup>2</sup> @					
889.49 2/3 - 14603/-					
4/15.3 (ii) Patch repair over bitumenous					
Holes do - do all complete job.					
Qty VTM B P.No - (42) - 37.50 M <sup>2</sup>					
@ 337 = 46 2/3 - 12655/-					
5/ Patch repair over bituminous					
Surface do - do all complete job.					
Qty VTM B P.No - (42)					
37.50 M <sup>2</sup> @ 356 = 18 2/3 - 13357/-					
6/ 7/15.7 (i) Maintenance of C/D					
works etc.					
Qty VTM B P.No - (42)					
2.0 M <sup>2</sup> @ 1109.67 2/3 - 2219/-					

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
8/15.9 Maintenance of Road signs do-do all complete job.					
8/15.9 Vtmb P.N. - (43) - D. 10 KM @ 1066 = 5032/- 107200					
10/15.11 Maintenance of 200 m 2 KM stones do-do all complete job. Dtp Vtmb P.N. - (43) - 0.120 KM @ 641 = 62 2/KM — 77200					
11/15.14(i) Cutting of branches of trees & shrubs etc. Dtp Vtmb P.No - (43) 11-0-N@ 105=393/- 105000					
11/15.12(ii) cutting of shrubs from roadway etc. Dtp Vtmb P.No - (44) - 4.0 N@ P. 6 = 472 /No — 26 = 0					
11/15.12(iii) Trimming of grass & weeds etc. Dtp Vtmb P.No - (44) - 10.0 M <sup>2</sup> @ 2 = 16 2/M <sup>2</sup> — 22.0 42					
11/15.13 White washing of lawpat wall of go work do-do all complete job. Dtp Vtmb P.N. - (44) 40.52 M <sup>2</sup> @ 16.54/- M <sup>2</sup> 667 = 00 742.29/-					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					15F-
					74229 = 00
Less 0 m per agreement left below					7423 = 00
					66806 = 00

Xin P  
27/03/24

C4P

JE

Pm - P  
27/03/24  
E6

Material statement