

4th year Maintenance Bill

Sch. XLV—Form No. 134

52

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work—	PMGSY Road Se				
Location—	Kharod, Haryana				
Agency—	Rajesh Kr.				
Agreement NO—	21 SEP/2018—20				
Actual Completion date—	10/2/20				
① Restoration of rain cuts.					127.58 M ³
② Making up shoulders					483.75 M ²
③ Repair of pot hole filled					
with 75 mm WPM					100.78 M ²
④ Patch repair over pot holes					
with 20 mm formix surface					100.78 M ²
⑤ Patch repair over bitumens					
sweep free.					100.78 M ²
⑥ Maintenance of C&G					
drain pipe culvert					6 NO.
⑦ Maintenance of road					
seepage					0.240 km
⑧ Maintenance of 200 M & km					
stone					0.280 km
⑨ Cutting of branches of					
trees					3 NO
⑩ Cutting of shoulders from					
roadway					11 NO
⑪ Trimming of grass and					
weeds					27 M ²
⑫ White washing of parapet					126 M ²

Continuation

Abstract of Cost

53

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Pavements -					
av. 100 P. - (52) 127.58 M ³					
CR 365.25/M ³					R 46597=00
② Making up shoulders					
av. 100 P. - (52) 483.75 M ²					
CR 54.16/M ²					R 26200=00
③ Repair of pot hole filled					
with 75 mm bitum.					
av. 100 P. - (52) 100.78 M ²					
CR 372.28/M ²					R 37519=00
④ Patch repairs over pot					
hole with 20 mm port mix					
surface. av. 100 P. - (52)					
100.78 M ² CR 206.22/M ²					R 30917=00
⑤ Patch repairs over bitum.					
surface. av. 100 P. - (52) 100.78 M ²					
CR 326.55/M ²					R 32910=00
⑥ Maintenance of CD main					
pipe. av. 100 P. - (52) 6 NO					
CR 1121.64 each					R 6790=00
⑦ Maintenance of road sign					
av. 100 P. - (52) 0.240 km					
CR 1087.62/km.					R 257=00
⑧ Maintenance of 200 M ² km					
stone. av. 100 P. - (52) 0.280 km					
CR 654.33/km.					R 183=
183=					R 186=00
⑨ Cutting of branches of					
trees. av. 100 P. - (52) 3 NO					
CR 107.48 each					R 322=00
Continuation					

Continuation