

5th Year Maintenance

Sch. XLV-Form No. 134 23

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
Name of work-	Maintenance of				
road from Meghu Sah house to					
Lo35 near	Madarsa under UTSMY				
Agency-	Sri Sanjeev Kumar				
	Dewivedi				
Agreement No-	13SBD/2018-19				
Date of start-	09/08/2018				
Date of completion-	08/08/2019				
Actual date of Completion-	04/08/2019				
5th Year Maintenance	05/08/2023 to				
Period	04/08/2024				
① Restoration of Rain c.					

1	X	6.00	X	1.15	X	0.30	=	1.72M ³
2	X	7.00	X	1.20	X	0.30	=	5.04M ³
2	X	6.00	X	1.20	X	0.25	=	3.60M ³
1	X	8.50	X	1.25	X	0.30	=	3.19M ³
3	X	7.00	X	1.20	X	0.30	=	7.56M ³
2	X	4.50	X	0.80	X	0.25	=	1.80M ³
1	X	7.50	X	1.28	X	0.25	=	2.40M ³
1	X	8.00	X	1.20	X	0.25	=	2.40M ³
1	X	6.50	X	1.10	X	0.30	=	2.14M ³
1	X	10.00	X	1.25	X	0.25	=	3.12M ³
1	X	5.00	X	1.20	X	0.30	=	1.80M ³
1	X	6.50	X	1.25	X	0.30	=	2.44M ³
2	X	8.00	X	1.28	X	0.25	=	5.12M ³
2	X	7.50	X	1.15	X	0.30	=	5.17M ³
Continuation								47.50M ³

Abstract of cast

26

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts					
Q-VTNB P23① =	47.50m				
P24③ =	39.12m				
	86.62m				
ck 359.74/m ² - R. 311612m					
② Maintenance of earthen Shoulder					
Q-VTNB P24② =	151.50m				
P25③ =	145.12m				
P25③ =	184.55m				
	481.17m				

ch 359.74/117 - h. 3/16/20

② Maintenance of earthen
Shoulder

Q-VTNB	$P_{24} \textcircled{2} = 151.50$	1
	$P_{25} \textcircled{3} = 145.12$	4
	$P_{25} \textcircled{6} = 184.55$	4
	481.17	12

cf 53.91/172 - K 25940 = a

(3) Maintenance of H.P. solvent

Q. VNB 124 (9) = 1 May

e _h	1104.35	each R	1104=00
		R	58.205=00

Less 10% below $\rightarrow$ 5820 = 00
Rs. 52385 = 00

~~9/16~~ 3/8/24

202
5/8/21
AF

C4P

Qml
12 | 8 | 24