

5th Year Maintenance

24

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Near Rajeswar Paswan house to near Pipal Trees under UTSNY					
Agency- Sri Sanjeev Kr. Dewivedi					
Agreement No- 14 SBD/2018-19					
Date of Start- 09/08/2018					
Date of Completion- 08/08/2019					
Actual date of completion- 04/08/2019					
5th Year Maintenance } 05/08/2023 to					
Period } 04/08/2024					

① Restoration of Rain cuts					
1 X	7.00	X	1.15	X	0.25 = 2.01H
1 X	8.10	X	1.25	X	0.30 = 3.04H
1 X	6.80	X	1.10	X	0.25 = 1.87H
1 X	7.50	X	1.15	X	0.30 = 2.59H
1 X	6.40	X	1.25	X	0.30 = 2.25H
1 X	8.25	X	1.25	X	0.25 = 2.58H
2 X	10.00	X	1.25	X	0.30 = 7.50H
1 X	8.10	X	1.20	X	0.30 = 2.88H
1 X	8.15	X	1.15	X	0.30 = 2.81H
1 X	7.15	X	1.20	X	0.30 = 2.57H
1 X	8.20	X	1.15	X	0.25 = 2.36H
1 X	11.50	X	1.25	X	0.30 = 4.31H
1 X	6.50	X	1.10	X	0.30 = 2.14H
Continuation					38.91H

Abstract of cast

28

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts					
R-VTHB P24(1) =		38.91M			
P25(3) =		37.57M			
P26(5) =		13.67M			
		90.15M			
c.h.		359.74M	K.		324312m
② Maintenance of earthen shoulder					
R-VTHB P25(2) =		105.57M			
P26(M) =		280.40M			
		114.74M			
		500.71M			
c.h.		53=91M	K.		26993=m
③ Maintenance of H.P. culvert					
R-VTHB P27(7) =		114M			
c.h.		1104=35/cach K.			1104=m
			K.		60,528=m
Less 10% below →					6053=m
			K.		54,475=m
5/8/24					
on					
5/8/24					
AB					
C.H.P.					
@ rate					
12/8/24					