

1st year Maintenance Bill

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work:- Maintenance of work					
Room Pena Field TO					
Paina Nath Asthan					
Hote hue Rakchire					
Lokas Chanda Amby					
Sadar Tak (NABARD)					
Agency:- Raja Kumar Singh					
Khushan, Hamnagar					
Ag. No. - 64 SAD/2017-18					
D. O. Start - 31.03.2018					
D. O. Completion - 30.03.2019					
A.D.O. Completion - 24.04.2022					
① Restoration of rain cuts					
Berms with soil - -					
- - - - - 12					
12 x 3.20 x 1.125 x 0.45 -					19.44 m ³
6 x 4.25 x 1.00 x 0.35 -					7.65 m ³
3 x 6.50 x 1.125 x 0.300 -					6.58 m ³
5 x 5.20 x 1.100 x 0.250 -					7.15 m ³
2 x 12.00 x 1.125 x 0.310 -					8.10 m ³
8 x 10.10 x 0.700 x 0.250 -					14.80 m ³
10 x 7.20 x 1.00 x 0.300 -					21.60 m ³
4 x 4.60 x 1.125 x 0.35 -					6.21 m ³
7 x 3.00 x 1.200 x 0.250 -					6.30 m ³
6 x 3.35 x 1.125 x 0.250 -					5.653 m ³
					101.934 m ³

Continuation

ABSTRACT OF COST

① Restoration of said cuts
with soil moorum -

V.M.B.P. 57 Qty 101.934 m³
@ Rs 361.86/m³ — Rs 36885 = 83

② Making up of Berms/
Shoulders stripping
loose soil - - - B.P.

V.M.B.P. 58 Qty 382.325 m³
@ Rs 54.61/m³ — Rs 20878 = 76

③ Periodical renewal to
existing bifurcations
Sisheer - - - B.P.

V.M.B.P. 58 Qty 31.854 @ Rs 64.96/m³
Continuation Rs 2068 = 97

59833 = 56

Material Statement

$E_{\text{Po}} \rightarrow 133.80 \text{ m}^3$

slip $\rightarrow 1.50 \text{ m}$

15/02/23
JB