

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर
e-mail- eerwdsamastipur@gmail.com

पत्रांक 18553/20 दिनांक 20/8/24

प्रेषक:— कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:— शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।
महाशय,
उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।
अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाय।
अनु०—यथोक्त।

विश्वासभाजन

20/8/24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर
Rev.
20.8.24

FROM GFR 19-A**(See Government of India's Division (I) below Rule- 150)****Form of Utilization Certificate upto 19.08.2024****PIU- E.E., R.W.D. Works Division, Samastipur**

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. n.-92, dt.16.08.2024	1281484613.00	Certified that out of Rs.1281484613.00 received upto 19.08.2024 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.1219956615.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs.61527998.00 remaining unutilized at the end of period under report.
			1,281,484,613.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.


Executive Engineer
Works Division Samastipur
Rural Works Dipartment


20.8.24

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur																		
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/km)	Thickness of Bitumen Layer (In MM)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks	
				Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/SA/SAM/23/0013	32010102072	SH 101 - GADOPUR	2328 & 04.05.2023	1.160	89.820	72.270	7.076	12(MBD)2023-24	10.07.2024	Complete	3220	25	5.0	0.00	0.00	65.25000	Complete

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS


 Executive Engineer
 RWD (W) Div. Samastipur
 26.8.24

Steco Analyzer

Name of Customer : Bhola Ray

Name of Work/ Road : SH T01 - Godopur

Lab Job number : 52

Date : 10.08.2024

Section No. : 52

Test Date : 10.08.2024

Machine No : 396

Start S No :

Start E No :

Weather :

Start Location :

End Location :

Road Name : SH T01 - Godopur

Road Type : (R) RURAL ROAD

Side :

Ultraviolet Range : 1745 To 4000

Dist Range : 0 To 1.2

Equation : $Y = 0 * X^2 + 1.136 * X + 132.5$

Interval : 1000 mm/km

Print

Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\USER\Desktop\10081316.Xls, Section No. :52, Eqn : $Y = 0 * X^2 + 1.136 * X + 132.5$

Name of Customer : Bhola Ray, Name of Work/ Road : SH T01 - Godopur, Lab Job number :52

UV
mm/
km

1745

0

0.1

0.2

0.3

0.4

0.5

0.6

0.7

0.8

0.9

1

1.1

Distance * 1000 m

08/08/24
52

Bhola Ray

Name of Road :- SH T01 Godopur

Section no.-52

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km				
10/8/24	13:11:3	52	0.1	240	0	2400	2858	ROAD	25.848734	85.647538	Normal
10/8/24	13:11:40	52	0.1	260	10.1	2600	3086	G	25.84882	85.647588	Normal
10/8/24	13:12:7	52	0.1	250	10.1	2500	2972	G	25.8482126	85.647501	Normal
10/8/24	13:12:39	52	0.1	230	10.1	2300	2745	G	25.8474088	85.6473877	Normal
10/8/24	13:13:8	52	0.1	240	10.1	2400	2858	G	25.8464363	85.6472847	Normal
10/8/24	13:13:42	52	0.1	260	10.1	2600	3086	G	25.8454735	85.6471996	Normal
10/8/24	13:14:8	52	0.1	250	10.1	2500	2972	G	25.8446754	85.6472542	Normal
10/8/24	13:14:48	52	0.1	260	10.1	2600	3086	G	25.8444289	85.6482191	Curve
10/8/24	13:15:12	52	0.1	250	10.1	2500	2972	G	25.8434355	85.648376	Normal
10/8/24	13:15:44	52	0.1	240	10.1	2400	2858	G	25.8424401	85.6485028	Normal
10/8/24	13:16:11	52	0.1	230	10.1	2300	2745	G	25.8416151	85.6480391	Normal
Total =			1.1	Km	Avg. 2930.73						

Executive Engineer
R.W.D.(W) Division,
Samastipur

08/08/24
13:16:11