

2nd year maintenance.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
Work - Maintenance of Road from Sak Jitola to Rajpur ch-65 Bridge more.					
Agency - Shri Sharada Construction.					
Rel. Agreement No - 114/SRD/2019-20					
Date of Commencement - 25/01/2020					
Actual Date of Completion -					
(1) Restoration of Rain cuts					
199.61 m ³ P - (6)					
@ 379.59/m ³					75770.20
					75770.20
(2) Making up Berms/shoulder stripping excess soil.					
1113.80 m ² P - (7) L.H/W - 1113.75 m ²					
@ 57.01/m ²					63495.20
(3) Pot Repair over Bituminous Surface					
117.24 m ² P - (8) H.V. + 117.19 m ²					
@ 239.33/m ²					28052.20
(4) Maintenance of CD Slope Culvert.					
S nos P - (8)					
@ 2273.45/m ²					11367.20
					1178683.20

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5/9) Maintenance of Road sign					
0.4 km	1 km	P-8			
21054.28/km					Rs 41720
(6/10) Maintenance of 200 m x 1 km slope					
0.500 km	P-8				
2614.10/1 km					Rs 30420
(7/11) i) Cutting of branches of trees & shrubs					
7 nos	P-8				
2106.12/no					Rs 74320
(8/11) ii) Cutting of shrubs from Railway					
33.0 nos	P-8				
26.51/no					Rs 21520
(9/11) iii) Trimming of Grass & weeds					
18.0 m ²	P-8				
2.17/m ²					Rs 3920
					Rs 18040120
@ Add 12% G.S.T					Rs 2164820
@ Add 1% Less					Rs 180420
					Rs 20385320
Below 0.09% (-)					Rs 18320
					Rs 20367020
By <i>[Signature]</i>					
By <i>[Signature]</i>					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
N/WORKS- Maintenance of Road from San Ji Gola to Kupali Stabs Distaya more Agry- Shri Shakti Construction of Agreement no. 114/1130/2019-20 Date of Commencement- 25/2/2020 Date of Completion.					
(1) Restoration of Alignment					
233.40 m ³ P- (12)					
@ 378.59/m ³					Rs 88596=0
(2) Making up Bumps shoulder stripping excess soil					
1113.81 m ² P- (13) 1st to 1113.75 m ²					
@ 57.01/m ²					Rs 63495=0
(3) Repair of pot holes filled with 75 mm BM					
13.17 m ³ P- (13)					
@ 8989.63/m ³					Rs 118516=0
(4) Pot Repair over Bituminous 20 mm m.s.s					
175.61 m ² P- (13)					
@ 230.19/m ²					Rs 40463=0
					Rs 311070=0

Continuation

2/1/07 02-20

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5/5) POC Repair over Bitumen Grout Surface 20 mm M.S.S					
175.61 m ² P-(13)					4203620
@ 239.37/m ²					4207720
(6/6) Maintenance of CP slab type unit.					
5 nos P-(14)					
@ 2273.47/m ²					1136720
(7/7)					
(8/9) Maintenance of Road C/S					
0.500 km P-(14)					
@ 1054.28/km					52220
(8/10) Maintenance of 200mm & 150mm stone					
0.590 km P-(14)					
@ 614.10/15m					36520
(9/11) i) Cutting of Branches of Trees & Shrubs					
7 nos P-(14)					
@ 106.12/m ²					74320
(10/11) ii) Cutting of Shrubs from H/Way					
33 nos P-(14)					
@ 6.51/m ²					21520
					36631820

Continuation

836318: ~

Continuation