

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	3rd Year maintenance.				
N/Work:-	main ⁿ of Road from				
	Babhangama Kurmi to				
	to Baya Jagdishpur.				
N/Agency:-	rats infrate.				
Agg. No:-	38 SBD/2015-16				
D.O.S:-	18/05/2015				
D.O.C -	17.05.2016				
A.D.O.C -	10.08.2018				
	Date of measurement				
(vi)	Restoration of rain				

cut - do - do - E/I				
9x	12x	0.90x	0.30=	29.16m ³
8x	11x	0.80x	0.30=	21.12m ³
7x	13x	1.10x	0.30=	30.03m ³
9x	11x	1.20x	0.30=	35.64m ³
8x	12x	1.10x	0.30=	31.68m ³
7x	11x	1.20x	0.30=	27.72m ³
9x	10x	0.90x	0.30=	24.30m ³
7x	12x	1.30x	0.30=	32.76m ³
8x	11x	1.1x	0.30=	29.16m ³

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				R/S =	177837=00
				less below 7.52).	Rs - 13373=00
				R/S =	164464=00
				S-90 5' 2"	
				J.B.	
				material statement	
				E/C = 470.88 m ²	
				stone metal = 3.31 m ²	
				stone chips = 2.65 m ²	
				S-90 = 123.48 100	
				S-90 5' 2"	
				J.B.	
