

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>4th Year maintenance.</u>					
N/Work:- main ⁿ of Road					
from Raabhangama					
Kurmi tola to					
Boya Jagdishpur					
N/Agency:- rate estimate					
Agg No:- 38 SBD/2015-16					
A.O.S - 18/05/2015					
D.O.C - 17/05/2016					
A.D.O.C - 10.08.2018					
<u>Date of measurement</u>					

(Y) Restoration of rain					
cuts - do - do - 6/1					
12x	12x	1.1x	0.30	47.52m ³	
10x	11x	1.2x	0.30	39.60m ³	
11x	13x	1.1x	0.30	47.19m ³	
12x	11x	1.20x	0.30	47.52m ³	
15x	13x	1.10x	0.30	64.35m ³	
16x	11x	1.20x	0.30	63.36m ³	
18x	10x	1.30x	0.30	70.20m ³	
				Qty	379.74m ³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Scanned with CamScanner