

5th year Maintenance

H A A D (M) DIVISION
31st EDITION

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road from L033 to Bankat under Minusy (Brs)					
Agency - M/S Uttar Bitor Const. Co.					
Agreement No - C SEP 2018-19					
Date of start - 25/06/2018					
Actual date of completion - 30/05/2019					
5th year Maintenance - 31/05/2023 to					
Period					30/05/2024
① Maintenance of carriageway shoulder					

2	x	8.40	x 1.25 =	20.50 ft
4	x	10.40	x 1.20 =	48.00 ft
3	x	7.10	x 1.70 =	23.43 ft
5	x	9.40	x 1.28 =	57.60 ft
3	x	6.50	x 0.90 =	17.55 ft
2	x	8.25	x 1.15 =	18.975 ft
4	x	6.50	x 1.20 =	31.20 ft
2	x	7.50	x 0.80 =	12.00 ft
4	x	7.50	x 1.25 =	37.50 ft
5	x	8.20	x 1.20 =	49.20 ft
3	x	7.25	x 1.15 =	25.00 ft
4	x	12.40	x 1.25 =	60.00 ft
6	x	6.50	x 0.90 =	35.10 ft
4	x	8.50	x 1.10 =	37.40 ft

Continuation

37
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	B.F.	R. 451.085=			

Less 10.y. below $\rightarrow 451.08 = 0$
 R. 451.05,977=

A 30/65/4	Area	soil
50		12

cap
various type
30/65

Material statement

(i) Soil - 312.7711

(ii) Chipp - 35.9311

(iii) Sand - 2.6911

(iv) Boulders - 2.36111

A 30/65/4