

2nd year Maintenance

7

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Mangli Baitha ke ghar to Barwa (MUNSY-Gien)					
Agency- Vijay Kumar Jaiswal					
Agreement No- 60 SBD/2019-20					
Date of work order- 19/03/2020					
Date of completion- 18/03/2021					
Actual date of completion- 05/02/2022					
2nd Year Maintenance Period 06/02/2023 to 05/02/2024					
① Restoration of Raincuts					
1 X 10.00 X 1.25 X 0.30 = 3.75M ³					
2 X 7.00 X 1.10 X 0.25 = 3.85M ³					

1	X	12.00	X 1.20	X 0.30	=	4.32M ³
1	X	7.10	X 1.15	X 0.25	=	2.04M ³
2	X	6.00	X 1.25	X 0.30	=	4.50M ³
2	X	8.00	X 1.20	X 0.30	=	5.76M ³
1	X	5.10	X 0.90	X 0.25	=	1.15M ³
						25.37M ³

② Maintenance of earthen Shoulder

1	X	8.10	X 1.20	=	9.72M ³
2	X	10.00	X 1.25	=	26.25M ³
1	X	6.50	X 1.20	=	7.80M ³
2	X	7.50	X 1.10	=	16.50M ³
2	X	8.00	X 1.15	=	18.40M ³
3	X	6.00	X 1.10	=	19.80M ³

Continuation

98.47M³

Abstract of cost

10

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts					
Q-VTMBP 7① =				253711 ³	
P 8③ =				18.9111 ³	
				44.2811 ³	
c h. 379.5911 ² - R.					16808=00
② Maintenance of earthen Shoulder					
Q-VTMBP 7② =				98.4711 ²	
P 8⑤ =				99.2311 ²	
P 9⑧ =				165.4711 ²	
				363.1711 ²	
c h. 572611 ² - R.					20,704=00
③ Maintenance of bituminous Surface					
Q-VTMBP 8④ =				38.4111 ²	
c h. 267=4811 ² - R.					10274=00
④ Maintenance of slab culvert					
Q-VTMBP 9⑥ =				3 Nos	
c h. 2273=47/each R					6820=00
⑤ Cutting of branches of trees					
Q-VTMBP 9⑦ =				2 Nos	
c h. 106=12/each R					212=00
⑥ cutting of shrubs					
Q-VTMBP 9⑧ =				9 Nos	

Continuation

54818=00

