

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Contractor					
Rajesh Kumar Roy					
Name of P. no.					
concrete/maintenance					
SI. No. of from					
Sonamata Shital					
Farmvir under					
Hazard					
Date of Actual Completion					
30/12/15					
Period - 1st year					
- maintenance					
Date of Agreement					
3-56y. below					
Date of entry -					
15/10/16					
1) Roast from 01 <sup>st</sup>					
rain cut withdrawal					
as per all completed					
so 1 M <sup>3</sup> M <sup>3</sup> A-86					
65-81 m <sup>3</sup> @ 278 = 86 Ks - 18252/-					
2) making up of Berry					
shoulder loss of					
material available					
wide 1 M <sup>3</sup> D- 86					
436-2 cm <sup>3</sup> @ 43-90 Ks - 19292/-					


Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BF A 37 6442-a
<u>3) Patch Repairing Wall</u>					
Painted Surface					
20 mm Asbestos Premix					
Caret with Seal					
Coat					
42.66 m <sup>2</sup>	291.30	12427			
<u>4) Maintenance of Cols</u>					
Work done					
3 nos @ 76.28	152.23	092			
<u>5) cutting of Branches</u>					
3 nos @ 62.52	187.56	2002			
<u>scrubbing of Shrub</u>					
13 @ 4.17	55.2				
<u>6) Trimming of Grass</u>					
33.00 m @ 123.91	4062				
<u>8. whitening White Wash</u>					
all parapets					
63 nos @ 112.38	717-				
					/
	B	53297=			
less 18 per					
<u>Agreement</u>					
3-£64.	1900=	6			
					51497=00

90

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		BF	51497268		
<del>DR</del>				FLGV	
14/08/2017				IS/10/1b	
DBZ					

  
 Executive Engineer  
 RWD Works Division  
 Mahesh Dabholkar

  
 30/8/24