

Record Entry

4th year maintenance

1

Name of Work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement -
 (These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of contractor:-	Rajesh Kumar Roy				
Name of Road:-	Sarma Chowk - 40				
	Sitalrampur Tak, Path				
Head:-	4515 Nabard Yona.				
Date of completion:-	30.12.2015				
Agreement Rate:-	3.56% below				
period:-	31.12.2018 to 30.12.2019.				
	4th year maintenance				
Date of Entry:-	24.11.19				

① Restoration of Rain cuss with				
Soil, Moorum, gravel do do				
2x10 nos	3.00m	0.65m	0.30m	11.70
2x10 nos	3.00m	0.5m	0.30m	13.50
2x15 nos	3.00m	0.70m	0.30m	18.90
2x10 nos	3.00m	0.60m	0.30m	10.80
2x20 nos	3.00m	0.70m	0.30m	25.20
2x10 nos	3.00m	0.65m	0.30m	11.70
2x10 nos	3.00m	0.60m	0.30m	10.80
				102.60 m ³
				say 101.90 m ³
② making up of berm / shoulder do do				
2x10 nos	3.00m	1.00m		600
2x2 nos	3.00m	0.90m		108
				708.0 m ²

Continuation say 707.63 m²

Particulars	Details of actual measurement				Contents of area,
	No.	L.	B.	D.	
③ Repair of pot holes filled.					
With 75mm BM do-do					
10 nos $\times 1.60m \times 1.20m \times 0.075m = 1.440$					
10 nos $\times 1.80m \times 1.10m \times 0.075m = 1.485$					
20 nos $\times 1.20m \times 1.10m \times 0.075m = 1.980$					
10 nos $\times 1.70m \times 1.20m \times 0.075m = 1.530$					
10 nos $\times 1.60m \times 1.20m \times 0.075m = 1.440$					
10 nos $\times 1.30m \times 1.00m \times 0.075m = 0.975$					
					8.85m ³
				Say	8.84m ³
④ patch repair over pot holes					
With 20mm premix carpet					

with seal coat type B'					
do-do					
10 nos $\times 1.60m \times 1.20m = 19.20$					
10 nos $\times 1.80m \times 1.10m = 19.80$					
20 nos $\times 1.20m \times 1.10m = 26.40$					
10 nos $\times 1.70m \times 1.20m = 20.40$					
10 nos $\times 1.60m \times 1.20m = 19.20$					
10 nos $\times 1.30m \times 1.00m = 13.00$					
					118.0m ²
				Say	117.94m ²
⑤ patch repair over Bitum					
- with surface to fill					
2mm premix carpet with					
Seal coat type B' do do					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F	RS 2	29568 =
(8/10) Maintenance of zoom and					
bu post do do					
Qty vide TMB item no (8) page (3)					
1.64 km					
1.64 km @ RS 477.81 = RS 7832					
(9/10) Cutting of branches of trees and shrubs do do					
Qty vide TMB item no (9) page (3)					
03 nos					
03 nos @ RS 66.52 = RS 1992					
(10/11) Trimmer of grass and					
needs for the shoulder					
do do					
Qty vide TMB item no (10) page (3)					
32.0 m ²					
32.0 m ² @ RS 1.39 = RS 442					
(11/12) White washing of parapet walls of CD work do do					
Qty vide TMB item no (11) page (3)					
63.0 m ²					
63.0 m ² @ RS 11.38 = RS 7172					
					RS 231311 =
Less RS for Approx 3.56% below					RS 82352
					RS 223076 =

Continuation

25.11.19
JE

Executive Engineer
RWD Works Division
Manjhauli Bakhari
24/01/24