

4th Year Maintenance Bill

20

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/1/1/1/1	Narenpur	Buzurg	AA Hajipur		
	Mahva	3/4-49	Birna	Lakhen	
	Sen	hale	mebouda	chawla	
	Purendra	3	K	phar to birna	
	Prakhamik	Vidudalay.			
Agency:	Ashok Kumar.				
Agreement No.:	77/SB/2019-20				
D.O.S -	22/08/2019				
D.O.C -	27/05/2020				

(1) Restoration of Rain wtr.					
2	4	14	M	0.80	0.30 = 26.88 m ³
2	2	5	M	0.80	0.120 = 12.00 m ³
1	3	3	M	0.90	0.40 = 10.80 m ³
2	2	10	M	0.50	0.30 = 13.44 m ³
					Qty: 63.12 m ³

(2) Making up of berm shoulder					
striking excess soil					
2	7	10	M	0.90	201.60 m ²
2	5	10	M	0.80	160.00 m ²
2	3	10	M	0.85	61.20 m ²
2	3	10	M	0.55	56.10 m ²
Continuation					Qty: 417.90 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
42.00 m Dry wide p.m.u. 22					
(2) 17.16 / —				Rx:	721 : 00
					76 : 00
				To: 97	515 : 00
less for below 10 m (G) :					9751 : 00
				To: 87,764	: 00
Muzartu SE 27/5/24				Single	
				27,05.24	
				AP	
				Verd Sanjay 23/8/24	