

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maintenance					
Received from	Maintenance Received				
from Nazipur Railway Committee					
41 to Nazipur Talmagole					
under MM GSY Scheme					
Aug - Sanita Q. Dem.					
Andau - 22/8/2020 - 29					
Dated 29/8/2020 - 30/10/2020.					
Dated 1/11/2023					
① Restoration of Rain cuts					
using all GSY/other					
7 x 15m x .75 x .30 = 23.625 m ²					
	Area 21.05 m ²				

2. making up of Bms.					
Shallow using all					
10 x 15m x .75 = 112.50 m ²					
	Area 108.59 m ²				
3. making Barren					
drum					
2 x 297m = 594m					
4. Road making					
using all					
New asphalt lane work 14/13					
2nd 13	59.40 m ²				
	11/11/2023				
	making				
① Earth -	38.00 m ³				

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
		Abstract of cost				
1. Restoration of Benin						
cut & with all complements						
Quar/ Secumbe	14	23				
320		21.05 m ²				
Qu/ 286.14/m ²					8/28 =	
2. making up of Benin						
with all complements						
Quar/ Secumbe	14	23				
320	2	108.59 m ²				
Qu/ 57.36/m ²					6229 =	
3. making of Benin						
chamir uniside						
Quar/ Secumbe	14	23				
320	3	594 m				
Qu/ 2.69/m					1598 =	
4. GA of Benin making						
with all complements						
Quar/ Secumbe	14	23				
320	4	59.40 m ²				
Qu/ 735.44/m ²					43685 =	
					59640 =	
Add 124.657 + 14 m					7753 =	
3.12					90	
					67483 =	
Less 164.6 m					10797 =	
					56685 =	