

1st year maintenance

21

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Kichanpur Bhola Rai keshar					
SH 59 to Raghunathpur Chowk					
(S62) talc.					
Agency - M/s Bhagwati Construction					
Ag. No - 113 (SBD) / 2022-23					
D.O.W - 16.09.2022					
Actual D.O.C - 20.06.2023					
(1) Restoration of Rain cut -					
	6 x 5.50 x 0.90 x 0.35 =				10.39
	11 x 4.25 x 1.10 x 0.30 =				15.43
	8 x 6.10 x 1.15 x 0.35 =				19.64
	12 x 5.10 x 1.20 x 0.30 =				21.60
	7 x 3.65 x 1.00 x 0.35 =				8.94
					76.00 m ³
(2) Maintenance of earthen					
shoulder —					
	12 x 7.50 x 0.75 —				67.50
	17 x 5.00 x 0.80 —				68.00
	20 x 6.00 x 0.85 —				102.00
	16 x 8.00 x 0.80 —				102.40
	11 x 7.00 x 0.90 —				69.30
					409.20 m ²
(3) Maintenance of Hume pipe					
Culvert —					
	2 x 1 = 2.00 m ²				

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty wide THB R (22)					
8.0 Hvy @ R 113.99/cen R					912 =
(6) Topping of gravel -					
Qty wide THB R (22)					
86 L 957.75 m ² @ R 2.33/m ² R					2218 =
					B. 58960 =
Acclt Glt + L. cur (131.1) — R					7665 =
Acclt S. Fee — — — R					432 =
					B. 67057 =
key 1.23 % Below — — — R					825 =
					R. 66232 =
862 20/6/14 0.8					

Makeup

Qty. 130.864 m³~~862~~
~~20/6/14~~
~~0.8~~