

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) Maint of 11.11 - do					
Qty = 2 Nos					
(4) Maint of slab - do per					
Qty = 1 No					
(5) Maint of sign board - do per					
Qty = 0.31 Km					
(6) Maint. of stone post - do per					
Qty = 0.38 Km					
(7) Cutting branches of trees - do per					
Qty = 6 Nos					
(8) Cutting of shrubs - do do per					
= 26 Nos					
(9) White - washing of parapet - do do					
fall - comp 1/4					
2 x 4 x 6.15 x 0.60 = 29.52 m ²					
2 x 2 x 6.15 x 0.40 = 9.84 m ²					
2 x 4 x 0.40 x 0.60 = 1.92 m ²					
					= 41.28 m ²
(P.T.O.)					

Continuation

[illegible]

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
④ Mgmt. of slab - culvert					B.P. 110, 0682
— do — wide DMB					
Psq = 1 No					
⑤ Mgmt. of Sugar Guard					B.P. 2309 = 24 / B.P. 2309 = 20
— do — wide					
Psq =					
⑥ Mgmt. of 200m, km					B.P. 1074 = 51 / B.P. 274 = 50
stone post - do					
⑦ Cutting of 0.31 km					
— do — wide 59 = 0.31 km					
Psq = 6 Nos					
⑧ Cutting of 0.639 km					B.P. 106 = 52 / B.P. 639 = 50
— do — do — do					
⑨ wide 0 mb					
Psq = 26 Nos					
⑩ wide 54 — B.P. 170 = 10					
⑪ wide washing of					
— do — do — do					
Psq = 41.28 m					
⑫ wide 27 / B.P. 671 = 20					
— do — do — do					
Psq = 1, 14, 330 = 20					

Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L	B	
(10) Patch repair - side				
PLO =		119.4 cm		
	@ R _p	291293	- R _p	34856 m
	= R _p	1,49,186	> w	
Deduct @ 0.07%				
As per 898(-)	R _p	30 > w		
	= R _p	149,156	> w	
By Sd/-	Sd/-			
Date 18.10.24	Signature			
V.V.C				

	Material Statement
①	W600 = 244.38 m ³
②	Stone Aggregate = 3.23 m ³
③	Bitumby = 0.275 m ³
	244.38
	3.23
	0.275