

MMGSY
(SC)

459 Dayday for Tha

Schedule XLV-Form No. 134

Udakishtungan

DIVISION

Gudabacca

SUB-DIVISION

Measurement Book

Shayam to 10/9

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work: Maintenance of Road					
from Vishu Bank Path					
TO Baski Tola.					
under NMGSY-SC					
Agency: Chandan ko Jha					
Bhagalpur					
Ag. No. - 651555/2018-19					
Date of Start - 02.01.2019					
D.O. Completion 01.10.2019					
A.D.O. Completion 20.09.2019					

① Restoration of rain cuts				
with soil measure -				
- - - C12				
1x 12.00 x 1.125 x 0.500 -				6.75 m ³
2x 6.70 x 1.100 x 0.400 -				5.896 m ³
5x 5.10 x 0.700 x 0.300 -				5.355 m ³
1x $\frac{(12.00 + 8.10)}{2} \times 0.65 \times 0.400 -$				2.613 m ³
5x 4.70 x 1.125 x 0.300 -				7.931 m ³
1x $\frac{(15.00 + 11.50)}{2} \times 1.100 \times 0.500 -$				7.288 m ³
2x 22.00 x 0.60 x 0.300 -				7.92 m ³
1x 10.60 x 1.00 x 0.300 -				6.36 m ³
2x 30.00 x 0.500 x 0.200 -				6.00 m ³
1x $\frac{(18.00 + 14.00)}{2} \times 0.750 \times 0.200 -$				3.00 m ³
				59.113 m ³
Continuation Limit = 41.96 m ³				

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Patch repair over bituminous surface					
- - - - - cell					
Area same as above -					
					46.975 m ²
⑤ Maintenance of CD work in slab Culvert -					
- - - - - cell					
					1.00 MS
⑥ Maintenance of Road					
Signs - - - - - cell					
					0.22 km
⑦ Maintenance of 200 m and 100 stone -					
- - - - - cell					
					0.26 km
⑧ Cutting of branches of trees and shrubs					
- - - - - cell					
					2.00 MS
⑨ Cutting of shrubs from road ways -					
- - - - - cell					
					6.00 MS

Continuation

1000m
5/10/23
S.E

4th year Maintenance

ABSTRACT OF COST

79

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of rain cuts with soil - - -					
√mBP-76 Qty 41.96 m ³					
CRS 352-21/m ³ - - -					Rs 14779-00
② Making up of Berms/ Shoulders - - -					
√mBP-77 Qty 233.10 m ²					
CRS 51-71/m ² - - -					Rs 12054-00
③ Repair of Pot holes filled with 75 mm - -					
- - - - -					
√mBP-77 Qty 46.975 m ³					
CRS 319-57/m ³ - - -					Rs 15012-00
④ Patch repair over bituminous surface - - -					
√mBP-78 Qty 46.697 m ²					
CRS 211-75/m ² - - -					Rs 9860-00
⑤ Maintenance of CD work in slab culvert - -					
- - - - -					
√mBP-78 Qty 1.0 nos					
CRS 2287-2/each - - -					Rs 2287-00
⑥ Maintenance of Road signs - - -					
√mBP-78 Qty 0.22 km					
CRS 1067-44/km - - -					Rs 2355-00
Continuation					Rs 54227-00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Maintenance of 200m and km stone — —					
— — — — —					
Am BP 78 Qty 0.26 km					
CRS 566-07/km — —					Rs 147-00
⑧ Cutting of branches of trees — — — —					
— — — — —					
Am BP 78 Qty 2.0 m					
CRS 104-08/ea — —					Rs 209-00
⑨ Cutting of stumps from road ways — —					
— — — — —					
Am BP 78 Qty 8.0 m					
CRS 6542/ea — —					Rs 39-00
					54622-00
Less for below @ 10% — —					Rs (-) 5462-00
					49160-00
<i>[Signature]</i> 05/10/23 J.E <i>[Signature]</i> 05/10/23 A.E					
Material Statement					
E/w →	66.40 m ³				
S/Agg →	4.26 m ³				
S/chips →	1.26 m ³				
C/sand →	0.28 m ³				
Bitumen	100.00 kg				
Emulsion	9.34 kg				

Continuation

[Signature]
05/10/23
J.E