

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd Year Maintenance					scr
Name of work - Maintenance of					
road from Renar sakshara					
road to Nandurga					
Agency - Sri Ram prasad sirsi					
Agreement No - 3013-221					2019-20
actual date of completion - 25/8/21					
① Restoration of Rain					
coat ceiling 50/1					
Modern etc. plaster					
complete job					
4x 6.0m x 1.0m x 0.3m					7.20 M ³
6x 5.0m x 0.9m x 0.3m					8.10 M ³
7x 3.0m x 0.85m x 0.3m					5.35 M ³
3x 6.0m x 1.0m x 0.3m					5.40 M ³
				TOTAL	26.05 M ³
② Mucking of earthen shoulder					
16x 5.0m x 1.10m					88.00 M ²
4x 6.0m x 1.0m					24.00 M ²
8x 5.0m x 0.90m					36.00 M ²
				TOTAL	148.00 M ²
③ Patch repair over bituminous					
surface ceiling 20mm					
preparation carpet, base					
6x 1.5m x 0.90m					8.10 M ²
4x 3.0m x 0.25m					3.00 M ²
7x 2.0m x 0.85m					11.90 M ²
				TOTAL	23.00 M ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
(1)	Restoration of Raincoat				
	Wider TMS per (43) el (1)				
quantity:	26.05 m ³	378-2201 m ²			9853 = u
(2)	Maintenance of earthen				
	Slope				
	Wider TMS per (43) el (2)				
quantity:	60.44 m ²				
	3742 m ²				
quantity:	148.44	57-121 m ²			8453 = u
(3)	patch repair on				
	bituminous surface				
	Wider TMS per (43) el (3)				
quantity:	23.0 m ²	307-341 m ²			7073 = u
(4)	Maintenance of earthen				
	drain in cul				
	Wider TMS per (43) el (4)				
quantity:	730 m ²	239-248 m ²			1943 = u
(5)	Maintenance of road				
	Wider TMS per (43) el (5)				
quantity:	0.14 km ²	1066.30 km ²			1342 = u
(6)	Maintenance of 200 m ³ km				
	stone				
	Wider TMS per (43) el (6)				
quantity:	0.18 km ²	648-291 km ²			113 = u
(7)	Culverts & Bottom of pipe				
quantity:	0.1 m ²	103-239			103 = u

Continuation
u 704 276982 u

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance work					
Name of work - Maintenance of					
road from Benarsak					
Shikara Road to					
Nauranga					
Agency - Sri Ramprasad Singh					
Agreement No - SRD-22/19-20					
actual date of completion - 25/8/21					
(1) Restoration of Raincur					
with 300/8 Medium					
in all complete m					
10x 6.0m x 1.0m x 0.3m = 18.0 m ³					
9x 5.0m x 1.10x 0.3m = 14.85 m ³					
					Total = 32.85 m ³
(2) Maintenance of earthen					
sidech in all					
10x 6.0m x 0.90 m = 54.0 m ²					
12x 5.0m x 1.0m = 60.0 m ²					
6x 8.0m x 0.95 m = 45.60 m ²					
					Total = 159.60 m ²
(3) Repair of potholes					
with filler with 75mm					
in all complete m					
4x 3.0m x 1.0m x 0.075 = 0.90 m ³					
6x 4.0m x 1.10x 0.075 = 1.98 m ³					
					Total = 2.88 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					ABSTRACTION
(1) Restoration of drainage					
					Width T.M. 1.25 m
Qty: 32.85 M ²				32.85 M ²	12426
(2) Maintenance of cartway					
					Shoulder in cut
					Width T.M. 1.25 m
Qty: 159.6 M ²				159.6 M ²	51.88
					80.52 = 121 M ²
					8673 = 10
(3) Repair of potholes					
					Width T.M. 1.25 m
Qty: 2.88 M ²				2.88 M ²	
					2-3 M
					10702 = 391 M ²
					25364 = 10
(4) Patch repair over pot hole					
					Width T.M. 1.25 m
Qty: 30.0 M ²				30.0 M ²	8678 = 10
(5) Patch repair over					
					between two drains
					Width T.M. 1.25 m
Qty: 30.0 M ²				30.0 M ²	9220 = 10
(6) Maintenance of road sign					
					Width T.M. 1.25 m
Qty: 0.18 M ²				0.18 M ²	1066 = 50 M
					192 = 10
(7) Maintenance of M.E. Stone					

Continuation

Width T.M. 1.25 m

Qty: 0.22 M² 648 = 24 M

143 = 10

64698 = 10

