

3rd Year Method Bill

78

Sch. XLV Form No. 134

Particulars	Totals of actual measurement				Contents or area
	No	L	B	D	
Name of work = <u>Method of Road</u>					
<u>from Kerejara</u>					
<u>Road to Lalmer</u>					
Agency = <u>M/K Royal Infra Ltd.</u>					
Approved - <u>01/02/2019-20</u>					
Commenced - <u>31/02/2019</u>					
Completion - <u>30/02/2020</u>					
Actual Completion - <u>28/09/2020</u>					
Rate - <u>10th Bonus</u>					

Attested

17 Restoration of soil -

Cut - do

20x1.20x0.50	x	0.30	=	3.84
25x1.15x0.60	x	0.30	=	3.60
24x1.05x0.35	x	0.30	=	5.18
25x1.00x0.50	x	0.30	=	6.85
12x1.50x1.00	x	0.30	=	3.25
12x1.20x0.90	x	0.30	=	7.65
9x1.45x1.25	x	0.30	=	4.84
5x1.30x1.85	x	0.30	=	2.15
6x1.25x1.00	x	0.30	=	3.15
3x0.90x0.90	x	0.30	=	0.73
5x0.75x0.50	x	0.30	=	0.53

(Continuation)

Sch. XLV Form No. 134

[illegible]

(Continuation)

Particulars	Details of actual measurement			Contents or area
	No.	L.	B.	
1) Patch repairs of pithy				
width zone no. PMC				
Qty ASP (11) = 135.82 m ²				
@ 2 m. 39/100 = 34022				
2) Patch repairs over				
bituminous surface				
do				
Qty ASP (12) = 135.82 m ²				
@ 268.80/100 = 36523				
6) main of 100 m				
Qty ASP (13) = 2.00 m ²				
@ 1109.67/100 = 2219				
7) main of 200 m				
do				
Qty ASP (14) = 0.36 m ²				
@ 1069.40/100 = 384				
8) main of 200 m				
Qty ASP (15) = 0.43 m ²				
@ 461.54/100 = 207				
9) Cutting of branches of				
tree & shrub				
Qty ASP (16) = 1.10 m ²				
@ 105.39/100 = 122				
10) Cutting of shrub				
from boundary				

(Continuation)

Sch. XLV-Form No. 134

[illegible]

Attested

Prifam

28.08.24

~~Abhinit~~
121124

12-10112A

$$T - \sqrt{2}$$

(Continuation)