

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E E R-W B Borsani

Name of Block/Road :- Kadwa, Khumharwa to Nariyaliya

### A. For Road

1. Damage Location/Chainage :-

2. Damage Length :-

0.05 Km

3. Nature of Damage (Length Wise)

(i) Breach :-

0.5 Km

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :-

fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :-

Brick Ball Road

(ii) Equipment/Tools Being Used in Restoration Works :-

T.C.B. Translari

(iii) Restored Length

In open Area :-

✓

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

### B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/  
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

✓

Signature of Inspector  
(Official Seal)

29/11/2014