

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E RWB (W) Sikkhanta (Dhaka)

Name of Block/Road :- Dhaka Ghorashan PWD Road to Khairwan

A. For Road

Damage Location/Chainage :-

Damage Length :- 0.238 km

Nature of Damage (Length Wise) (i) Breach :-

(ii) Crust Damage :- 0.238 km

(iii) Only Flank Damage :-

Whether traffic fully/Partially obstructed : ~~fully obstructed~~

Details of Restoration :-

i) Material Being Used in Restoration :- Brick Bricks / Stone Metal

ii) Equipment/Tools Being Used in Restoration Works :- Tractor / Trolley / Gen / Roller

iii) Restored Length In open Area :-

In habitation Area :- 0.238 km

v) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1) Damage Location/Chainage :- ✓

2) No. of Span Damage :- ✓

3) Length of Span :- ✓

4) Nature of Damage (Pier/Abutment/
wing Wall/Approach Road Damage) :- ✓

5) Details of Restoration :- ✓

i) Material Being Used in Restoration :- ✓

ii) Equipment/Tools Being Used in Restoration Works :- ✓

iii) Restored Length :- ✓

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Yogiraj
Signature of Inspector
(Official Seal)

E.E. And. Rwan

EE

30.11.24
EE/Dhaka

[Signature]
30.11.24

A. E. Ranawat.