

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E RWD(W) Sikharua (Dhaka)	
Name of Block/Road :- Dhaka Phulwanga Road to Persa	
<b>A. For Road</b>	
Damage Location/Chainage :-	
Damage Length :- 0.098 km	
Nature of Damage (Length Wise)	(i) Breach :-
	(ii) Crust Damage :- 0.098 km
	(iii) Only Flank Damage :-
Whether traffic fully/Partially obstructed :- Obstructed	
Details of Restoration :-	
i) Material Being Used in Restoration :- Brick Bats / Stone Metal / Gravel	
ii) Equipment/Tools Being Used in Restoration Works :- JCB / Tractor / Roller / Trolley	
ii) Restored Length	In open Area :-
	In habitation Area :- 0.098 km
iv) If Restoration work done in habitation Area give Reason :-	
<b>B. For Bridge (Size of Bridge/Culvert)</b>	
1) Damage Location/Chainage :-	x
2) No. of Span Damage :-	x
3) Length of Span :-	x
4) Nature of Damage (Pier/Abutment/ Wing Wall/Approach Road Damage) :-	x
5) Details of Restoration :-	x
i) Material Being Used in Restoration :-	x
ii) Equipment/Tools Being Used in Restoration Works :-	x
iii) Restored Length :-	x
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

29.11.24.  
A.E. Rahman.

Signature of Inspector *[Signature]*  
(Official Seal) 29.11.24  
EE, RWD, Persa  
Dhaka