## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs: - Rurd works Depth works (Dir.) Dhate, shik horns.
Name of Block/Road: - Chirry
. For Road
. Damage Location/Chainage: At 1.00KM Chaingl from start Point.
. Damage Length :- DALSKM
Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage: - crust Damge ( >5 welta)
(iii) Only Flank Damage: - Frankdamile 25 mgk
hether traffic fully/Partially obstructed: Fortially obstructed.
Details of Restoration:-
) Material Being Used in Restoration: - Bruick, bots, Rabbish, Local bound.
i) Equipment/Tools Being Used in Restoration Works :-
ii) Restored Length In open Area: - ofen Noa.
In habitation Area :-
v) If Restoration work done in habitation Area give Reason:-
For Bridge (Size of Bridge/Culvert)
1) Damage Location/Chainage:-
2) No. of Span Damage:- X
3) Length of Span :- X
4) Nature of Damage (Pier/Abuttment/ K
Ving Wall/Approach Road Damage):-
5) Details of Restoration:-
) Material Being Used in Restoration :- 💢
i) Equipment/Tools Being Used in Restoration Works :- 🛇
iii) Restored Length :- 🔀
verall Grade of Restoration work (Satisfactory/Unsatisfactory):-
7

29.11.24. A.E. Ranaul. Signature of Inspector

(Official Seal)

29:11:24 E/D/a