

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Rural work Dept. (MWD) Chikmagalur Taluk	
Name of Block/Road :- Chiralya	
A. For Road	
Damage Location/Chainage :- At Ch. 0.000m from start point.	
Damage Length :- 0.065 km	
Nature of Damage (Length Wise)	(i) Breach :- Berches & crust both damaged.
	(ii) Crust Damage :- —
	(iii) Only Flank Damage :- —
Whether traffic fully/Partially obstructed :- Fully obstructed.	
Details of Restoration :-	
i) Material Being Used in Restoration :- Brick bats with rubbish.	
ii) Equipment/Tools Being Used in Restoration Works :- JCB, Roller, Tractor.	
iii) Restored Length	In open Area :- In open area.
	In habitation Area :- Partially in habitation.
iv) If Restoration work done in habitation Area give Reason :- Outside open.	
B. For Bridge (Size of Bridge/Culvert)	
1) Damage Location/Chainage :- — X	
2) No. of Span Damage :- — X	
3) Length of Span :- — X	
4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :- — X	
5) Details of Restoration :- — X	
i) Material Being Used in Restoration :- — X	
ii) Equipment/Tools Being Used in Restoration Works :- — X	
iii) Restored Length :- — X	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-	

[Signature]

29.11.24

A.E. Romant.

[Signature]
29.11.24
EE/Dhaka

Signature of Inspector
(Official Seal)

[Signature]
29.11.24
EE, RMD Rapant.