## INSPECTION REPORT FOR MOTORABLE WORK

	TOTAL WORK
Name of PIUs:- E.E.R	WD Barsoi
Name of Block/Road :- Kadwa	WD Barsoi / minopusto pureb Tolq mainfus
A. For Road	Imanpur
1. Damage Location/Chainage :- 25	· 313348£, 87.488011
2. Damage Length :- 0.950 km	
3. Nature of Damage (Length Wise)	(i) Breach:-
	(ii) Crust Damage :-
	(iii) Only Flank Damage:- CH: 400 to 450
whether traffic fully/Partially obstruct	ted: - July ebstraction.
4. Details of Restoration:-	
(i) Material Being Used in Restoratio	
(ii) Equipment/Tools Being Used in I	Restoration Works: - unstilled labour, F-F loade
(iii) Restored Length	In open Area:-
	In habitation Area:-
(iv) If Restoration work done in habi	tation Area give Reason :-
B. For Bridge (Size of Bridge/Ci	
(1) Damage Location/Chainage:-	
(2) No. of Span Damage:-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttme	ent/
Wing Wall/Approach Road Damage	e) :-
(5) Details of Restoration:-	
(i) Material Being Used in Restorati	on:-
(ii) Equipment/Tools Being Used in	Restoration Works
(iii) Restored Length :-	
	(G. i. f. etcry/I Insatisfactory) :-
Overall Grade of Restoration wo	Signature of Inspector  (Official Seal)  F. F. B. S.
	Signature of Inspector
	(Official Seal)
•	(Official Seal) F. F. Bon & 1