

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E-E RWD Barsoi

Name of Block/Road :- Kadar / paschim to 19 Goriyari to Riga Glet via Choti Tola -

A. For Road

1. Damage Location/Chainage :- 257195130
87-083644,

2. Damage Length :- 0.045 m

3. Nature of Damage (Length Wise) (i) Breach :- ☒ 0-045 m
(ii) Crust Damage :-
(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- brick bat, Robbrik

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor

(iii) Restored Length In open Area :- 0.045 m
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

29/11/2014
Signature of Inspector
(Official Seal)