

1st Year 32nd Maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No	I	II	D	
N/A - Maintenance of					
road from Mangar					
Zila and Uga					
Kharangpur - Lamli					
Main road to					
Barhara Mai					
- Dola - Lok Path					
Agency - Karan Kumar Singh					
Agg No - 08 SBD / 18 - 9					
Date of Commencement - 30/07/19					
Date of Completion - 29/04/20					

①	Restoration of				
	Rain Curb				
	$60 \times 2.40 \times 0.70 \times 0.30 =$				30.24
	$41 \times 1.40 \times 0.80 \times 0.30 =$				13.78
	$20 \times 4.00 \times 0.80 \times 0.25 =$				16.00
	$21 \times 2.10 \times 0.80 \times 0.30 =$				10.58
②	$24 \times 2.00 \times 1.10 \times 0.20 =$				10.56
	Total =				81.16 m ³
	Maintenance of				
	Shoulder				
	$8 \times 4.00 \times 0.80 =$				25.60
	$9 \times 6.00 \times 0.90 =$				48.60
	$7 \times 5.00 \times 0.80 =$				28.00
	$17 \times 8.00 \times 0.70 =$				95.20
	$28 \times 4.00 \times 0.80 =$				90.40

Continuation

[illegible]