

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
name of work - Repair of roof from Railway Gunh' 19 to Gunh' Bhoginathyaadav 70/9.					
Agency - Sanat 124700					
Agreement No - 112300/18-19					
Date of work - 19.11.2018					
Actual Completion - 03.07.2019					
<u>Record Entry</u>					
1) Restoration of roof cut with soil					

3x	3.60	x 0.90	x 0.30	2.92
4x	2.90	x 1.10	x 0.30	3.82
6x	3.50	x 0.80	x 0.30	5.04
7x	2.80	x 0.85	x 0.30	5.00
5x	4.90	x 0.90	x 0.30	6.62
6x	3.60	x 0.80	x 0.30	5.18
7x	3.30	x 0.95	x 0.30	6.58
9x	3.95	x 1.10	x 0.30	11.72
Total				46.90

2x	6x	4.60	x 0.80	44.16
2x	9x	3.90	x 0.90	63.18
2x	7x	5.80	x 0.70	56.84
2x	12x	4.20	x 0.95	95.76

Continuation

Total 259.94

Continuation