

5th year maintenance

57

sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Pipe in					100m
Road to Channukha Tola					
2. Name of Agency: M/S J.B. Construction					
3. Agreement No: 169/SBD/2018-19					
4. Actual dt. of completion: 01.11.2019					
— measurement as below —					
① Restoration of rain cuts					
1 with soil - 100m					
1x	20.50	x	0.90	x	0.30 = 5.535
1x	18.90	x	0.85	x	0.30 = 5.140
1x	20.80	x	0.72	x	0.30 = 4.492
1x	30.0	x	0.68	x	0.28 = 5.712
2x	20.60	x	0.72	x	0.30 = 8.899
3x	30.0	x	0.65	x	0.30 = 17.55
6x	30.0	x	0.62	x	0.30 = 33.48
1x	20.60	x	0.58	x	0.30 = 3.584
1x	20.95	x	0.62	x	0.30 = 3.896
1x	20.0	x	0.60	x	0.30 = 3.60
1x	2.50	x	0.72	x	0.30 = 0.540
1x	2.90	x	0.73	x	0.30 = 0.640
1x	1.20	x	0.50	x	0.30 = 0.180
					Qty = 93.248 m ³
					Say Qty = 93.22 m ³
② maintenance of earthen					
2 shoulder - 100m					
Qty =	5x	30.0	x	0.90	= 135.0
	6x	30.0	x	0.80	= 144.0

Continuation C.U. Qty = 279.0 m³

P.T.O.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
sem area, thickness of 2.5mm is exclusive					BPH 154506=0
clu - E14					
Qty = 231.90 m ² wide					
Trms Page (60)					
@ 755 = 53 / m ²					174,830=0
total					329336=0

~~Ran~~
~~28.10.2024~~
~~J.E~~

material statement

(i)	Earth	—	170.90 m ³
(ii)	Bitumen-90	—	532.27 Kg
(iii)	Stone chips	—	7.192 m ³

~~Ran~~
~~28.10.2024~~
~~J.E~~