5th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement No.	L.	B.	D.	Contents of area
1. Name of work: maintenance of road & drain panchayat Bhawan Jagdishpur to Baginagri mochi Tola					
2. Name of agency: Subodh Kumar Sharma					
3. Agreement No.					
4. Date of completion: 25.09.2019					
Measurement as below					
(1) Restoration of drain (cuts with soil-clean)					
	1x	2.98 x 0.90 x 0.30			= 0.804
	2x	6.0 x 0.85 x 0.30			= 3.06
	3x	10.50 x 0.82 x 0.32			= 8.265
	4x	9.50 x 0.72 x 0.30			= 8.208
	4x	9.80 x 0.68 x 0.32			= 8.529
	2x	8.50 x 0.70 x 0.30			= 3.570
	2x	7.85 x 0.68 x 0.28			= 2.989
	1x	2.98 x 0.90 x 0.30			= 0.804
	1x	1.10 x 0.50 x 0.30			= 0.165
	1x	1.50 x 0.60 x 0.30			= 0.270
	1x	1.10 x 0.62 x 0.30			= 0.205
				Qty =	36.869 m³
				Say Qty =	36.72 m³
(2) maintenance of earthen shoulder de-silt					
	1x	30.0 x 0.90			= 27.0 m²
					27.0 m²

Continuation

C.O. Qty =

P.T.O.

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					46736=00
			BP Qty =		12425=00
(5) maintenance of slab					
& type culvert-double					
Qty = 2.0 Nos side					
			TMB Page (16)		
@ Rs 2336=82/each				— Rs	4674=00
(6) maintenance of room					
& RM stone double					
Qty = 0.40 Km side					
			TMB Page (16)		
@ Rs 728=66/Km				— Rs	291=00
(7) providing cure					
& laying of hot applied					
thermoplastic compound					
2.5 mm thick double					
Qty = 80.60 m² side					
			TMB Page (16)		
@ Rs 770=48/m²				— Rs	62101=00
				Rs	113802=00
Less 10.0% below				— Rs	11380=00
				Rs	102422=00

15.10.2024

Scanned with CamScanner