

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th floor maintenance					
on Mr. Pill					
① Name of Works - Maintenance of road from Nijji					
3rd subya to Dharanpur					
② Name of Agency					
M/S Kumar Construction					
③ Agreement No - 26/2024					
④ Date of work start					
11/11/2024				9/11/23	
⑤ Date of completion					
				8/11/24	
① Restoration of gull cuts etc. all completed					
$4 \times 12.60 \times 1.10 \times 0.30 =$					16.632
$4 \times 13.60 \times 1.10 \times 0.30 =$					17.952
$5 \times 9.70 \times 1.10 \times 0.30 =$					16.485
$4 \times 11.70 \times 1.10 \times 0.30 =$					15.444
$3 \times 13.50 \times 1.10 \times 0.30 =$					13.860
$5 \times 12.30 \times 1.10 \times 0.30 =$					20.295
$6 \times 14.60 \times 1.10 \times 0.30 =$					28.908
					128.574

Continuation 24/11/24 127.580

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Making up of beams/Shoulders Soil etc. all completely					
5x 13.70 x 1.00 =					68.50m ²
4x 12.90 x 1.00 =					51.60m ²
5x 12.60 x 1.00 =					63.00m ²
4x 11.80 x 1.00 =					47.20m ²
5x 12.60 x 1.00 =					63.00m ²
4x 12.00 x 1.00 =					50.00m ²
6x 13.90 x 1.00 =					83.40m ²
5x 11.70 x 1.00 =					58.50m ²
4x 12.90 x 1.00 =					51.60m ²

5x 11.80 x 1.00 =	59.00m ²
4x 12.70 x 1.00 =	50.80m ²
5x 12.60 x 1.00 =	63.00m ²
4x 11.80 x 1.00 =	47.20m ²
5x 12.60 x 1.00 =	63.00m ²
4x 12.00 x 1.00 =	50.00m ²
6x 13.90 x 1.00 =	83.40m ²
5x 11.70 x 1.00 =	58.50m ²
4x 12.90 x 1.00 =	51.60m ²

③ Repair of pot holes filled with 75mm etc. all completely

1x 10.50 x 2.00 x 0.05 =	1.05m ³
2x 7.50 x 2.40 x 0.05 =	2.70m ³
2x 7.90 x 2.10 x 0.05 =	2.48m ³
1x 5.50 x 2.25 x 0.05 =	0.92m ³
4x 9.50 x 2.50 x 0.05 =	7.12m ³

Continuation

14.803m³
13.18m³

Particulars	Details of actual measurement	Contents
(4) Particulars	Details of actual measurement	Contents
1 x 10.50 x 2.25	2	21.37m
2 x 7.50 x 2.40	2	36.00m
2 x 7.90 x 2.10	2	33.18m
1 x 1 x 5.50 x 2.25	2	12.37m
4 x 9.50 x 2.50	2	95.00m
		Dty-137.50m
(5) Maintenance of work		
H-P (Culvert) etc. all		
Completely		
		Dty-11.00
(6) Maintenance of Slab		
Culvert etc. all complete		
		Dty-11.00
(7) Cutting of branches of		
trees and shrubs etc.		
all completely		
		Dty-3.00
(8) Cutting of branches etc.		
all completely		
		Dty-1.50
(9) White washing of		
walls etc. all		
Completely		

Continuation

ABSTAIN - if can't

- Continuation C-83, 256-

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				64-83	83,2562
					1241387
					124,222
(4) Patch repair of / Pot holes seal surface etc all completely Qty vide Tuss 11063 Qty 175.78 p2 @ 1/2.197-86 / p2 - 34,780					
(5) Maint. of L.T. works H.P. current etc. all completely Qty vide Tuss 11063 Qty 1110 @ 1095.22 / each - 10952					
(6) Maint. of Glutentva etc. all completely Qty vide Tuss 11063 Qty 1110 @ 2268.31 / each - 22682					
(7) Cutting of branches of trees and shrubs etc. all completely Qty vide Tuss 11063 Qty 1110					

Continuation of 603, 244,671
2455572

ckp liman 16.07.24 EE	at 16.10.24 total 3. 2,46,337 16.10.24 total 3. 2,38,981 2,39,972 917125 AE Liman
--	--

Scanned with CamScanner