

BLOCK - parsauni

ଅଫିସ ମମ୍ବସ୍ୟ (SC) P.M.S.S.Y ଥର-ଆବୃତ୍ତି ଆମା-ସେ
ମିପେଆନା ଡିପାର୍ଟମେଣ୍ଟ, (Maintenance)

Shedule XLV Form No. 134.

ଆମିର କାମ ବିମାଣ

DIVISION

କାମ ମାନ୍ଦିର ଦିଆରୀ

ଆମିର କାମ ବିମାଣ

SUB-DIVISION

କାମ ଆମ୍ବ ମାନ୍ଦିର, ମାନ୍ଦିର

Measurement Book

ALOCK KUMAR SENGH

MBNO

534

2nd year maintenance Bill

① Restoration of rain cuts/Besms with soil, moorum - —

Qty Vide AMBA(3) ①: 55.81 m³

(a) $A_s = 386.14 \text{ mm}^2$ $A_s = 21550 \text{ mm}^2$

② Making up of berms/shoulders stripping excess soil - — —

Qty. Vide Form BP (8) (2) = 246.30 m²

② As - $57.36/m^2$ As - 1428 = ∞

③ Maintenance of Bitumen

main seal - - -

Qty Vicle mmBP(8)(3) = 35.60 m²

② $A_s = 281.36 \text{ mm}^2$ $A_s = 10016 = \infty$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Maintenance of CD works (Hume pipe culverts) -					
Qty Vide MBP ④ = 2.0 NO					
② As. 1130.67/NO As.					2261=00
⑤ Maintenance of Road Sign -					
Qty Vide MBP ⑤ = 0.12 km					
② As. 1077.82/km As.					1292=00
⑥ Cutting of branches of trees and shrubs -					
Qty Vide MBP ⑥ = 2.0 NO					
② As. 109.74/NO As.					2192=00
⑦ White washing of parapet walls of CD works -					
Qty Vide MBP ⑦ = 41.30 m ²					
② As. 16.41/m ² As.					6782=00
⑧ Maintenance of 200 m and km stones -					
Qty Vide MBP ⑧ = 0.15 km					
② As. 628.23/km As.					94=00
⑨ Maintenance of Already planted trees for second year -					
Qty Vide MBP ⑨ = ^{25.0} 58.0 NO					
② As. 671=0/NO					16715=00
					38918=00
					87993=00
					65850=00
Add 12% GST + 1% C. (2136)					As. 11439=00
					8561=00
					As. 97432=00
					744112=00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				DF-	7441120 2943200 9m
				As-	7441120 7441120
less 0.11% as per Agg (-)				As-	11020 8220 9m
				As-	9932200 1432920
Rev 05/04/24 J.E				Rev 06/04/24 J.E	CLP Am 02/04/24

Material statement① earth - 55.81 m³② As. 23.71/m³③ Crushed Stone - 0.962 m³④ As. 528.73/m³

S-90 - 0.06764 MT

RS-2 - 0.00979 MT

Rev
05/04/24
J.E