

NH-30 To Lumsej Kalimandir Hote Neye
Lumsej Baram.
Shedule XLV Form No. 134.

Mumby (SC)

Bikramgarh

DIVISION

Dinara

PT 728172

SUB-DIVISION

Measurement Book

No: 530

Vitay Singh

2ND Year Maintenance

78

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - NH 30 to (crossed)					
Kali Mandir Hote Hue					
Crossed (crossed)					
Agency - vilay Singh					
Agreement No 21/ SBD/ 20-	21				
Actual Completion date	8/11/2				
① Restoration of					
soil cuts in soil					
2 x 2.6 m x 1.2 m x .30					1.870
4 x 3.1 m x 1.1 m x .30					13.64
6 x 4.3 m x .90 m x .30					6.96
8 x 5 m x 1.2 m x .30					14.4
2 x 2.5 x 1.1 m x .30					1.65
2 x 3.5 x .80 m x .30					1.68
3 x 1.9 m x .90 m x .30					1.539
1 x 2 m x .90 m x .30					0.54
					42.2
② Maintenance of					
earthen shoulder					
2 x 3.5 m x 1.2 m					8.4
2 x 4.5 m x 1.1 m					9.9
6 x 9 m x 1.2 m					64.8
8 x 5 m x 1.0 m					40
4 x 4.5 m x .90 m					16.2
18 x 3.6 m x 1.1 m					71.28
9 x 6.1 x 1.2 m					265.88

Continuation - 276.46

W. Kumar
29/11/23
A

29/11/23
DB

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8) Cutting of shrubs					
		P-79/6			
9 Nos @ 6.73 / m					61 ✓
(9) Trimming of grass					
		P-79/7			
4105 m ² @ 2.24 / m ²					9 ✓
					46304
Add Cost + L. cost 13% (+)					6020
					52324
					(A) ✓
Restoration 42.27 m x 4.23 m					185 ✓
Shrub	276.46 m	4.12 m			137
Potholes	32.75 m	14.94 m			49 ✓
					291 (B) ✓
Total A + B					
					52324 + 291 = 52615
Less 0.06% as per agreement					32 ✓
					52583 Rs 52585

Continuation