

5th year maintenance

Bill

71

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:-	PWD road No-12				
	Baibhangam to				
	milki under mro Gsy				
Agency:-	manish kumar				
	Bhagalpur				
Agg No	18/SB0/2017-18				
D/O/O/c-	13.03.2019				
Period-	14.03.23 to				
	13.03.24				

Rate - 10.00% below

Measurement Record

1) Restoration of rain cuts

17 x 3.00 x $\left(\frac{1.20 + 1.00}{2}\right) \times 0.30$	16.83
16 x 5.00 x $\left(\frac{1.40 + 1.20}{2}\right) \times 0.30$	31.20
12 x 4.00 x $\left(\frac{1.00 + 0.70}{2}\right) \times 0.30$	12.24
12 x 4.50 x $\left(\frac{1.00 + 0.80}{2}\right) \times 0.30$	14.58
15 x 4.00 x $\left(\frac{1.00 + 1.00}{2}\right) \times 0.30$	18.90
	93.75 "

2) making up of berms/shoulders

20 x 5.10 x 1.00	102.00 m ²
23 x 4.30 x 1.20	118.63 "
22 x 5.00 x 1.30	143.00
21 x 4.00 x 1.00	84.00

Continuation

Continuation