

Dakshin Tolg to LO22-Under
CH TO GTSNY

Schedule XLV-Form No. 13

Barro DIVISION

Barro SUB-DIVISION

1024

Measurement Book

Amil K. Singh
(Sivan) 18-19
61600

1st year 13034/-
2nd year 132/17.9.20
131/19.8.24
As 15460/-
cls.

3rd year Maintenance bill

30

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Maintenance of Road					
from Dakshin Tola					
to L022					
Agency:- Anil Kumar Singh					
Agreement no:- GLSBO/2018-19					
Actual Date of completion:- 15/02/2019					
Record measurement					
① Restoration of rainouts					
with Soil:-					
5 X 3.15m X 1.10m X 0.300m =					5.20m ³
7 X 2.50m X 1.00m X 0.280m =					4.90m ³
8 X 2.00m X 1.15m X 0.250m =					4.60m ³
4 X 3.00m X 0.900m X 0.280m =					3.02m ³
3 X 2.30m X 0.80m X 0.230m =					1.27m ³
9 X 2.40m X 0.75m X 0.240m =					3.89m ³
6 X 3.50m X 0.85m X 0.300m =					5.36m ³
					28.24m ³
② Making up loss of material:-					
8 X 2.80m X 1.15m =					25.76m ²
12 X 2.15m X 1.10m =					28.38m ²
6 X 3.40m X 1.00m =					20.40m ²
9 X 2.00m X 1.15m =					20.70m ²
5 X 4.50m X 1.10m =					24.75m ²
7 X 1.10m X 1.00m =					7.70m ²

Continuation