

स्टेड्स! - मनिरी

Parasbani Samthali to Bishampur
Mangli Poca.

Schedule XLV-Form No. 134

Agreement No:- 25/SBD/2021.

DIVISION

Agreement Amount:- 1,28,67,859/-

SUB-DIVISION

Krishnapalli Construction

Measurement Book

S25
26/06/20

MM654, ST

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
12. Paving on parapet					
	5X2X	6.150X	0.400		24.60 m ²
	5X4X	6.150X	0.600		73.80 "
	5X4X	0.400X	0.600		4.80 "
			Total		103.20 "
13. Mgmt of					
	16/07/24				
	R				
Assessment of work					
1. Restoration of rain cuts					
vide TMA by 51 =					106.29 m ²
@ B 386.14/m ²					R 41043.00
2. Making up Ben/shoulder					
vide TMA by 51 =					648.60 m ²
@ B 57.21/m ²					R 37204.00
3. Repair of pot holes vide					
TMA by 51 =					104.80 m ²
@ B 277.32/m ²					R 29063.00
4. Patch repair with MSS vide					
TMA by 51 =					104.80 m ²
@ B 247.93/m ²					R 25669.00
5. Maint of Hume pile vide TMA					
by 51 = 5 nos @ B 1130.67/ea					R 5653.00
6. Maint of road sign vide TMA					
by 51 = 0.20 km @ B 1077.84/km					R 267.00
7. Maint of 2 nos x km stone vide					
TMA by 51 = 0.30 km @ B 570.85/km					R 170.00
8. Cully & branches tree vide					
TMA by 51 = 3 nos @ B 109.74/ea					R 329.00

Continuation

1. Bank work 106.29 m³
 2. RS-1 0.029 m³
 3. S-80 : 0.199 m³
 4. Stone aggregate: 2.83 m³

Continuation