

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ON 3rd years maintenance Bill					
Name of work - 2 mcsy Alanya Path to Reharpur					
Name of agency - M/S Smith construction					
Agreement N - SBD - 13 - 2018-19					
Date of completion - 11/06/18					
Act & Ar D compo - 30/03/2020					
Actual Date of completion - 30/03/2020					
Date of Entry -					
17/8/23					

① Restoration of rancul with soil

$$2 \times 24.50m \times 1.0m \times 0.3m = 14.70m^3$$

$$2 \times 2 \times 30.0m \times 0.90m \times 0.3m = 32.40m^3$$

$$2 \times 28.0m \times 0.80m \times 0.3m = 13.44m^3$$

$$21.0m \times 0.85 \times 0.30m = 5.35m^3$$

$$65.89m^3$$

② Maintenance of earthen shoulder/Berm stripping excess soil

$$2 \times 4 \times 30.0m \times 0.80m = 192.0m^3$$

$$2 \times 23.50m \times 0.90m = 42.30m^3$$

$$2 \times 2 \times 30.0m \times 0.95m = 114.0m^3$$

$$2 \times 10.0m \times 0.75m = 15.0m^3$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of work</u>					
① Restoration of rainfall with soil					
65.80m ² vide TMS P56					
③ 361=86					23843=w
② Maintenance of Berm Shoulder					
363.30m ² vide TMS P56					
③ 54=61					19840=w
③ Patch repair on bit holes					
21.71m ² vide TMS P57					
③ 236=11					5126=00
④ Patch repair on bituminous surface					
21.71m ² vide TMS P57					
③ 248=76					5401=w
⑤ Maintenance of C/D work (H.P)					
2 Nos vide TMS P57					
③ 1076=79					2154=w
					56364=w
0.06% below as per Agreement					34=w
					R 56,330=w

Continuation

17/8/23
J.E