

3rd year maint. bill

45

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of works- Bateda high school					
to Gandigram.					
Agency - Sri Shaktikant Singh					
Agreement No- 82/SBD/20-21					
Actual Date of Completion - 2/07/21					
(1) Restoration of rainfalls -					
4 x 4.8 x 1.20 x 0.15 =					3.45
2 x 3.00 x 1.30 x 0.15 =					1.17
5 x 6.00 x 1.20 x 0.15 =					5.40
8 x 4.5 x 1.30 x 0.15 =					7.02
6 x 2.50 x 1.00 x 0.15 =					2.25
9 x 6.80 x 1.20 x 0.15 =					11.01
9 x 7.55 x 1.20 x 0.15 =					<u>12.23</u>
					<u>30.30 m³</u>
					= 42.53 m ³
(2) Making up berms / shoulder					
5 x 10.00 x 1.10 =					55.00
5 x 10.00 x 1.00 =					50.00
2 x 10.00 x 1.00 =					20.00
5 x 8.00 x 1.10 =					44.00
2 x 16.50 x 1.00 =					<u>33.00</u>
					<u>169.00 m²</u>
					202 m ²
					<u>168.75 m²</u>
(3) Repair of pot holes Gilled					
with 75 mm.					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract qty. of Cast</u>					
(1) Restoration of raincuts.					
vide qty. page no- 45					
42.53 m ³ @ 396.73/m ³ = 16873.00					
(2) making up berms/ shoulder.					
vide qty. page no- 45					
202.00 m ² @ 59.87/m ² = 12094.00					
(3) Repair of pot holes filled					
75mm.					
vide qty. page no- 45					
1.58 m ³ @ 10329.82/m ³ = 16320.00					
(4) Pot repair over holes					
With 20mm.					
vide qty. page no- 46					
21.00 m ² @ 273.99/m ² = 5754.00					
(5) pot repair over bituminous					
Surface 20mm.					
vide qty. page no- 46					
21.09 m ² @ 277.90/m ² = 5861.00					
(6) Maint. of road signs.					
vide qty. page no- 46					

~~Ramch~~
5/7/24
JE

6/3/24

material statement

- | | | | |
|-----|-------------|-------|----------------|
| (1) | Soil | 82.93 | m ³ |
| (2) | Stone chips | 0.56 | m ³ |
| (3) | Bitumen | 0.05 | mg |
| (4) | Emulsion | 0.005 | mg |

Ramish
5/8/24
26

Continuation