

कार्य का नाम: आर वकिल गल से विमुक्तपुत्र गल
का निजीकरण कार्य।

Schedule XLV Form No. 134.

आयुक्त संख्या: 3757/202-21 (mmmsd. mch.)
m.p.d


DIVISION

राज्य अभिजात, नारी अण्ड मंडल. इंदर नगर

SUB-DIVISION

Measurement Book

प्रमाणित किया जाता है कि इस मावपुस्त
पंजी में मशीन द्वारा मुद्रित (100) सौ पृष्ठ
हैं, जो सहायक अभियंता, ग्रामीण कार्य विभाग,
कार्य अवर प्रमंडल ~~उ.प्र. म.प्र. म.प्र.~~ के नाम
से निर्गत किया जाता है।


13/03/24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
~~कार्य अवर प्रमंडल~~ प्रमंडल, आरा

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd year maintenance</u>					
<u>N/W- Ara- Buxan Road to</u>					
<u>Bichumbung</u>					
<u>N/A- Birney kumar</u>					
<u>M/N- 03/MMA/GEW/180/10-2</u>					
<u>at 1st -</u>					
<u>at 1st -</u>					
<u>Detail of work</u>					
<u>1) Restoration of Rements/Berms</u>					
<u>with 201 measurement - 10/1</u>					
3x	3.00x	2.20	x 0.90	= 17.82 m ³	
2x	2.50	x 1.85	x 0.75	= 6.93 m ³	
2x	2.00	x 1.70	x 0.95	= 6.46 m ³	
<u>Qty = 31.21 m³</u>					
<u>2) making up of Berms / Shoulders</u>					
<u>surface strike - 10/1</u>					
3x	20.00	x 1.00	= 60.00 m ²		
4x	15.00	x 0.90	= 54.00 m ²		
2x	30.00	x 1.10	= 66.00 m ²		
<u>Total Qty = 180.00 m²</u>					
<u>3) Repair of pot holes filling</u>					
<u>with 75 mm - 10/1</u>					
4x	2.50x	1.20x	0.60	= 7.20 m ³	
1x	2.00x	1.50x	0.75	= 13.50 m ³	
4x	2.20x	1.40x	0.80	= 9.85 m ³	
<u>Total Qty = 30.55 m³</u>					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
① patching up road surface with 25 mm em — E/E					
Qty came at item no (03) P/41					
1.2. = 30.55 m ²					
② maintaining CD work					
Qty = 02 Nos					
③ painting on parapet wall					
④ Road marking with 107 of thermoblastic comp on BT surface					
UT1 = 2 x 465.4 x 0.10 = 93.08 m ²					
⑤					

Abstract of work					
① Restoration of Rumble — E/E					
Qty came at item no (01) P/41					
= 31.21 m ³					
② R.R. 404 = 06 / m ² R.R. 12,611.00					
③ marking up of R.R. / shoulder surface — E/E					
Qty came at item no (02) P/41					
= 180.00 m ²					
④ R.R. 60 = 28 / m ² R.R. 10,850.00					
⑤ Rep mnt. hot holes — E/E					
Qty came at item no (03) P/41					
= 30.55 m ²					
⑥ R.R. 362 = 15 / m ² R.R. 11,064.00					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ patch repair work on concrete — 70/c					
Qty same as item no ③					P/42
= 30.55 m ²					
② Rs. 240 = 83/m ²					Rs. 7,357 = 0
⑤ maintenance CD work					
Qty same as item no ③					P/42
= 02 Nos					
② Rs. 1166 = 58/cach					Rs. 2,333 = 0
③ Road marking on BT surf — 70/c					
Qty same as item no ③					P/42
= 93.4 m ²					
② Rs. 721 = 91/m ²					Rs. 130 = 0

Total Rs. 14,353 = 0

Add C.S.T @ 120. Rs. 13,302 = 0

Add C.C.P.S @ 120. Rs. 1114 = 0

S.Pee M 1,114 = 0

Total Rs. 1,26,943 = 0

Below 0.01% (-) Rs. 13 = 0

1,26,930 = 0

TS
07/12/24
AG

Continuation